



Technical Service Bulletin

Technical Service Bulletin: TSB170092

Released Date: 09-Feb-2019

New Exhaust Gas Temperature Sensor

New Exhaust Gas Temperature Sensor

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- QSK60 CM850 MCRS
- QSK60 CM2150 MCRS
- QSK60 CM2350 K116
- QSK60 CM2350 K117
- QSK60 CM2350 K121
- QSK60 G CM2358 K110 (Single Turbocharger)
- QSK60-G CM700 (Single Turbocharger)

Issue

Symptom:

- Exhaust gas temperature sensor Fault Codes: FC671, FC672, FC673, FC674, FC675, FC676, FC677, FC678, FC722, FC723, FC724, FC725, FC726, FC727, FC728, FC1521, FC1522, FC1523, FC1524, FC1525, FC1526, FC1527, FC1529, FC1532, FC1533, FC1534, FC1535, FC1536, FC1618, FC1619, FC2735, FC2736.
- Engine can shut down as a result of malfunctioning exhaust gas temperature sensor.

Root Cause:

- Fracture of exhaust gas temperature sensor platinum rhodium wire.

Resolution

- If exhaust gas temperature sensor has been found to have malfunctioned by published troubleshooting, install exhaust gas temperature sensor with orange sleeve. See corresponding Service Manual or Troubleshooting and Repair Manual. Reference Procedure 019-013 in Section 19.
- Existing exhaust gas temperature sensor part number has **not** changed.

Service Parts Availability

Service parts are available. See Table 1 for part numbers.

Table 1, Service Parts

Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
Sensor, Temperature (Diesel)	4954450	No	No	-
Sensor, Temperature (Gas)	2872378	No	No	-

Part Compatibility

Orange sleeved exhaust gas temperature sensor can be mixed with black sleeved exhaust gas temperature sensors in the same engine.

Part Identification

Improved exhaust gas temperature sensor can be identified by an orange sleeve. See Figure 1.



Figure 1, New Orange Sleeve Exhaust Gas Temperature Sensor.



Figure 2, Existing Black Sleeve Exhaust Gas Temperature Sensor.

Part Inventory Action

In stock parts are affected. See Parts Alert number MDC-12-17 for details.

Production Status

Implemented for production. See Table 2.

Table 2, Production Information

Sensor Part Number	Product	Engine Serial Number (ESN) First	Build Date ¹	Engine Plant
4954450	QSK60 CM2150 MCRS	33210400	05 Jul 2017	Daventry Engine Plant
2872378	QSK60 G CM2358 K110	33215731	17 Aug 2018	Daventry Engine Plant

¹Engine build date can be found on the engine dataplate.

Document History

Date	Details
2017-8-14	Module Created

Date	Details
2017-11-20	Removed QSK60 G CM2358 K110 (Twin Turbocharger Engines Only) from Product Affected section and added QSK60 G CM2358 K110 (Single Turbocharger) and QSK60-G CM700 (Single Turbocharger).
2019-2-4	Updated Table 2

Last Modified: 09-Feb-2019
