



Technical Service Bulletin: TSB190050

Released Date: 28-Mar-2019

Lifting Bracket Capscrew Corrosion

Lifting Bracket Capscrew Corrosion

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- QSK45 CM500
- QSK60 CM500
- QSK60 CM850
- QSK60 CM2150
- QSK60 CM2250 K112
- QSK60 CM2350 K116
- QSK60G
- QSK60G CM2358 K110

Issue

- Lifting bracket capscrew corrosion or damage.

Verification

1. Before lifting engine, remove and inspect lifting bracket capscrews.
 - See Corresponding Service Manual. Reference Procedure 016-001 in Section 16.
2. Inspect for any sign of galling or corrosion. See Figure 1 below.



Figure 1, Damaged and Corroded Capscrews.

Resolution

- If any sign of galling or corrosion is present:
 - Thoroughly clean threaded hole at cylinder block for the lifting bracket.
 - Replace any damaged or corroded capscrews with new lifting bracket capscrews. See Table 1 below.
- To help prevent damage or corrosion:
 - Verify lifting bracket cutout is properly aligned with lifting bracket mounting spacer. See Figure 2 below.
 - When positioning lifting bracket assembly between cylinder heads:
 - Position lifting bracket assembly cutouts towards center of engine. Lifting bracket notch will face outwards. See Figure 3 below.



Figure 2: Align Lifting Bracket with Mounting Spacer



Figure 3: Align Lifting Bracket Cutout Relative to Cylinder Head Position

Service Instructions

See Corresponding Service Manual. Reference Procedure 016-001 in Section 16.

Service Parts Availability

Service parts are available. See Table 1 for part numbers.

Table 1, Service Parts

Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
Capscrew	3089194	No	No	-

--

Document History

Date	Details
2019-3-27	Module Created

Last Modified: 28-Mar-2019
