



Technical Service Bulletin

Technical Service Bulletin: TSB200226

Released Date: 24-Nov-2020

New Long Oil Supply Tube Bracket Bolts

New Long Oil Supply Tube Bracket Bolts

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- QSK60 CM850
- QSK60 CM2150
- QSK60 CM2350 K116
- QSK60 CM2350 K117
- QSK60 CM2350 K121
- QSK60 CM2350 K136
- QSK60 CM2350 K137

Description of Change

The 4 single bolts used to support bracket part number 4101331 have been changed to a bolt and washer to prevent yielding of the bracket following torquing.

Reason for Change

The current bolt used to support bracket 4101331, when torqued, leads to damage to the bracket face. This can lead to a weaker bracket during operation. A single bolt has been replaced with a different bolt and washer part number which should be used to prevent yielding of the bracket. See part number table below.

Customer Communication

This change should only be made when an engine is overhauled or if the pickup bracket is removed for other repair/maintenance operations.

Service Instructions

The bolts should be torqued at the tube end of the slotted hole.

Service Parts Availability

Service parts are available.

Table 1, Service Parts

Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
Bracket Cap screw	3903990	No	No	3902460
Washer	3093778	No	No	

Part Compatibility

The new bolt and washer combination are compatible with all engines using bracket 4101331.

Service Tools and Training Available

No special tools required.

Production Status

Implemented for production.

Table 2, Production Information

ESN First	Build Date ¹	Plant
TBC	1-Jul-19	Daventry

¹Engine build date can be found on the engine dataplate.

Publications Affected/Associated Publications

No change to publications.

Document History

Date	Details
2020-11-19	Module Created

