



Technical Service Bulletin: TSB220016

Released Date: 04-Feb-2022

Leaking Coolant From Turbocharger Coolant Return Line

Leaking Coolant From Turbocharger Coolant Return Line

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- QSK60 CM2150 MCRS

Issue Summary

Symptom:

- Coolant leak

Root Cause:

- Incorrect hose clamp sizing

Verification

If a coolant leak from turbo coolant plumbing return line, Part Number 5375486, is observed, follow instructions in resolution section for fix.

Resolution

- If a coolant leak from turbo coolant plumbing return line, Part Number 5375486, has been observed replace the coolant plumbing hose with a new one, Part Number 5375486, and secure hose with quantity three of clip, Part Number 3649927.
- For proper removal and install instructions, see QSK60 CM2150 MCRS, Bulletin 4021530. Refer to Procedure 010-041 (</qs3/pubsys2/xml/en/procedures/56/56-010-041.html>) in Section 10.

Reason for Change

Original clips did **not** have proper fit which allowed fretting between turbocharger coolant hose and clamps resulting in coolant leak.

Service Parts Availability

Service parts are available. See Table 1 for part numbers.

Table 1, Service Parts

Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
CLIP	3657725	No	No	3649927

Production Status

Implemented for production. See Table 2.

Table 2, Production Information

ESN First	Build Date ¹	Plant
33226938	13 December 2021	Daventry Engine Plant

¹Engine build date can be found on engine dataplate.

Document History

Date	Details
2022-1-29	Module Created

Last Modified: 04-Feb-2022
