



Technical Service Bulletin

Technical Service Bulletin: TSB220078

Released Date: 13-Apr-2022

New Fuel Pump with Revised Outlet Check Valve

New Fuel Pump with Revised Outlet Check Valve

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

Engine:

- QSK60 CM2150 MCRS

Application and Rating:

- Construction engines with 2237Kw [3000 hp]

Description of Change

A new outlet check valve design has been integrated into the fuel pump assembly to improve reliability for 3000 hp construction applications.

Reason for Change

- To reduce fuel pump cavitation at the fuel pump outlet check valve and improve reliability, a new fuel pump part number has been released.
- The new outlet check valve design has improved elongated slots in the check valve to resolve cavitation issues.

Service Parts Availability

Service parts are available. See Table 1 for part numbers.

Table 1, Service Parts

Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
Fuel Pump	5540246	No	Yes	5541849

Production Status

Implemented for production. See Table 2.

Table 2, Production Information		
ESN Last	Build Date ¹	Plant
33227993	30 March 2022	Daventry
¹ Engine build date can be found on the engine dataplate.		

Document History

Date	Details
2022-4-12	Module Created

Last Modified: 13-Apr-2022
