



Technical Service Bulletin

Technical Service Bulletin: TSB220130

Released Date: 28-Jun-2022

Improved Exhaust Manifold

Improved Exhaust Manifold

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- QSK60 CM2150 MCRS

Description of Change

The exhaust manifold has received a casting change. The change improves the pouring process reducing the shrinkage porosity and core shift increasing component life. A change has also been introduced to the fillet radius connecting the main “trunk” to the cylinder head connecting branch. The radius of this area has been changed from 7 mm to 13 mm reducing the stress at this location.

Reason for Change

Customers have been reporting exhaust gas leaks coming from the exhaust manifolds caused by cracks. A factory led engineering project identified a high stress location in the manifold at the radius connecting the main trunk to the cylinder head branch. This high stress caused a crack to initiate that was then accelerated through the component by porosity and core shift.

Service Parts Availability

The exhaust manifold part number has **not** changed. The part numbers affected are exhaust manifold, Part Number 3642650 and 3642653.

Part Identification

Improved parts can be identified by the “B” stamping. See Figure 1 below.



Figure 1, Exhaust Manifold Identification Location.

Part Inventory Action

Use existing part number inventory before using the new part number.

Production Status

Implemented for production. See Table 1.

Table 1, Production Information

ESN First	Part Number	Build Date ¹	Plant
33228620	3642650B	6 June 2022	Daventry

¹Engine build date can be found on the engine dataplate.

Document History

Date	Details
2022-6-22	Module Created

