



Technical Service Bulletin

Technical Service Bulletin: TSB220211

Released Date: 12-Oct-2022

New Two Stage Turbocharger Frame

New Two Stage Turbocharger Frame

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- QSK60 CM2150 MCRS
- QSK60 CM850 MCRS

Description of Change

A new two stage turbocharger frame has been introduced with improved weld geometry. This change to the welds allows an enhanced distribution of the stresses throughout the component reducing high stress areas and cracks.

Reason for Change

Two stage turbocharger frame cracks have been reported. A factory investigation identified the initiation points of these cracks to be either at the weld or a high stress location adjacent to the joint.

Service Parts Availability

Service parts are available. See Table 1 for part numbers.

Table 1, Service Parts

Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
Two Stage frame	3642933	Yes	Yes	6311456

Part Inventory Action

Use existing part number inventory before using the new part number.

Production Status

Implemented for production. See Table 2.

Table 2, Production Information		
ESN Last	Build Date ¹	Plant
33229584	31 August 2022	Daventry
¹ Engine build date can be found on the engine dataplate.		

Document History

Date	Details
2022-10-11	Module Created

Last Modified: 12-Oct-2022
