



Technical Service Bulletin

Technical Service Bulletin: TSB230161

Released Date: 06-Sep-2023

New Turbocharger Bellows: Exhaust Leak

New Turbocharger Bellows: Exhaust Leak

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- QSK60 CM2150 MCRS

Description of Change

There is a new turbocharger bellows part number. The new turbocharger bellows has a smaller internal sleeve allowing improved clearance to the convolutes and exhaust connector. The design of the V-band mating face has also been changed to enable an improved contact with the V-band clamp.

Reason for Change

- There have been reports of exhaust gas leakage during engine operation. There is inadequate clearance between the turbocharger bellows inner sleeve and convolutes leading to contact. The resulting fretting takes place can either break parts away from the inner sleeve or cause a rupture of the convolute leading to exhaust gas leakage.
- V-band clamps can also become loose during operation. The assignable cause of turbocharger bellows malfunction was found to be the low contact area between the clamp and turbocharger bellows causing high stresses in the V-band clamp leading to component fracture.

Customer Communication

V Band clamp, Part number 201989, **must** be used or the V-band and/or turbocharger bellows can malfunction.

Service Instructions

Service parts are available. See Table 1.

Table 1, Service Parts				
Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
Bellows	4100758	Yes	Yes	6315830

Part Identification

New part can be identified by the part number stamped on turbocharger bellow flange. See Figure 1.

Part Compatibility

Only V Band clamp, Part number 201989, is compatible with the new part number.



Figure 1, Part Number Location on Turbocharger Bellows.

Table 2, Production Information		
ESN First	Build Date ¹	Plant
33232574	16 June 2023	Daventry

¹Engine build date can be found on the engine dataplate.

Document History

Date	Details
2023-8-25	Module Created

Last Modified: 06-Sep-2023
