



Technical Service Bulletin: TSB250016

Released Date: 10-Dec-2025

Engine Control Module (ECM) Calibration Code Change to Exhaust Gas Temperature (EGT) Sensor Thresholds: White Smoke

Engine Control Module (ECM) Calibration Code Change to Exhaust Gas Temperature (EGT) Sensor Thresholds: White Smoke

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- QSK60 CM2350 K116
- QSK60 CM2350 K121
- QSK60 CM2350 K135
- QSK60 CM2350 K136

Issue

Exhaust gas temperature (EGT) thresholds for setting fault codes in the engine control module (ECM) are too high to alert operators to early exhaust valve cracking and subsequent malfunction.

Symptom:

- White smoke from the exhaust and an underperforming cylinder at the affected position

Root Cause:

- EGT threshold values in the ECM calibration are set too high and do **not** illuminate warning lamps early enough to alert operators to valve malfunction.

Resolution

The ECM calibration codes have been changed to lower the EGT thresholds.

Description of Change

ECM calibration codes have been changed to lower the EGT thresholds from existing values. All products affected by this TSB share the same change. See Table 1.

Table 1, EGT Threshold Changes			
Fault Code Threshold	Existing EGT Value °C [°F]	New EGT Value °C [°F]	
Moderately Severe Level (Amber Lamp)	732°C [1349°F]	615 °C [1139°F]	
Most Severe Level (Red Lamp)	-	630 °C [1166°F]	
Reason for Change			
High exhaust gas temperature fault codes will alert operators of potential exhaust valve malfunction to mitigate further engine damage.			
Service Instructions			
For CM2350 engines, the new ECM calibration code is released for child 2 ECM. See Table 2.			
New ECM calibration codes are available as below:			
Table 2, QSK60 T4 ECM Calibration Codes			
QSK60 CM2350 ECM Codes (Child 2)			
CX60029.05	CX60149.05	CX60062.11	
CX60050.13	CX60170.02	CX60080.11	
CX60053.15	CX60173.02	CX60083.11	
CX60056.15	CX60176.02	CX60095.10	
CX60065.11	CX60179.02	CX60098.10	
CX60071.12	CX60182.02	CX60116.11	
CX60074.11	CX60191.02	CX60140.05	
CX60077.11	CX60193.02	CX60146.05	
CX60137.05	CX60217.02	CX60205.02	
CX60143.05	CX60059.11	CX60208.02	
Part Compatibility			
These ECM calibrations are cross compatible with existing parent and child calibrations.			
Production Status			
Originally implemented for production on Tier 2 and 4 products. See Table 3.			
Tier 2 products are no longer built with this change; therefore, the last engine build information is displayed in Table 4.			
Table 3, ESN First Information			
Engine Service Models	ESN First	Build Date ¹	Plant
QSK60 CM2150 MCRS	33237928	6 January 2025	Daventry Engine Plant
¹ Engine build date can be found on the engine dataplate.			

Table 4, Tier 2 Engines Information	
Engine Service Models	Last Build Date ¹
QSK60 CM2150 MCRS QSK60 CM850 MCRS	3 September 2025
¹ Engine build date can be found on the engine dataplate.	

Document History

Date	Details
2025-1-29	Module Created
2025-11-6	Non-Product Problem Solving (PPS)