



Technical Service Bulletin

Technical Service Bulletin: tsb070005	Released Date: 05-Feb-2007
Continuously Activated Fuel Lift Pumps	

Continuously Activated Fuel Lift Pumps

Core Issue

Electronic fuel lift pumps on QST30 engines operate in the KEY ON position without the engine operating. Extended periods in this state can cause damage to and eventual failure of the fuel lift pump.

Confirmation

All QST30 engines equipped with electronic fuel lift pumps in industrial applications.

Engine will **not** start or registers low power, once the fuel lift pump fails.

Reference the No Start symptom tree.

If the lift pump is operating without a cooling fuel flow for more than 30 seconds, the brush and commutator within the pump will sustain damage and eventually fail.

If the fuel pump fails, it **must** be replaced.

Resolution

Do not have the engine in KEY ON position for more than 30 seconds without operating the engine. If the engine needs to be left in the KEY ON position for troubleshooting purposes, disconnect the fuel lift pump. Connect the fuel lift pump when the engine is ready for normal operation.

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Last Modified: 05-Feb-2007
