



Technical Service Bulletin

Technical Service Bulletin: tsb090057	Released Date: 04-Aug-2009
Incorrect ECM Time (Key on time) in INSITE™ Fault Snapshot	

Incorrect ECM Time (Key on time) in INSITE™ Fault Snapshot

Core Issue

This Early Field Notification describes an issue with INSITE™ 7.3 electronic service tool and earlier versions displaying the ECM Time (Key on time) in the fault snapshot data incorrectly when the Real Time Clock is enabled.

Confirmation

- ISM CM876
- ISB4.5/6.7 ISD4.5/6.7 CM2150 SN (Euro 4.5)
- ISB4.5/6.7 ISD4.5/6.7 CM2150 SN (Euro 5)
- QSK38 CM850 - MCRS
- QSK50/60 CM850 - MCRS
- QSM 11 CM876 - Power Generation
- QSK38 CM850 -MCRS - Power Generation
- QSK50/60 CM850 - MCRS - Power Generation

The ECM Time (Key on time) is displayed incorrectly in the fault snapshot data in INSITE™ electronic service tool if the Real Time Clock is enabled in Advanced ECM Data. If the Real Time Clock is disabled, the ECM Time will be displayed correctly in the fault snapshot.

For example: if the Real Time Clock is enabled, the ECM Time is displayed incorrectly as 213274:47:16 (HH:MM:SS). If the Real Time Clock is disabled, the ECM Time is displayed correctly as 968:12:30 (HH:MM:SS).

None

None

None

Resolution

This issue is fixed with INSITE™ 7.3 electronic service tool Service Pack 1 and later versions.

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Last Modified: 04-Aug-2009
