



Technical Service Bulletin

Technical Service Bulletin: tsb100268

Released Date: 06-Apr-2004

New Cam Follower Roller

New Cam Follower Roller

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Technical Service Bulletin announces the release of a new cam follower roller for the QST30 engine. The new roller has an improved radius across the roller face and an improved hardening process to improve reliability. The new rollers are available individually or as a cam follower lever assembly.

Part Number Supercession		
Description	Old Part Number	New Part Number
Cam Roller	4068231	4068548
Lever assembly	3092499	4068611

There are no markings or visible differences between the old and new rollers. The new cam follower roller was implemented into production on September 24, 2003 with engine serial number first of 37209159.

Cummins Inc. recommends installing these new rollers and pins in place of old components during engine rebuild.

Note : This is a product improvement not subject to campaign.

Last Modified: 06-Apr-2004