



Technical Service Bulletin

Technical Service Bulletin: tsb100870

Released Date: 12-Oct-2009

New Valve Spring Rotator

New Valve Spring Rotator

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Technical Service Bulletin supersedes Service/Parts Topic 08T2-5. Replace Service/Parts Topic 08T2-5 with this Topic.

This Technical Service Bulletin includes additional information on the K19/QSK19 and cylinder head part numbers **not** covered in Service/Parts Topic 08T2-5.

This Technical Service Bulletin announces the introduction of a new valve spring rotator for use on K19, QSK19, K38, QSK38, K50, and QSK50 series engines. The new valve spring rotator is reduced in height by 0.5 mm [0.0197 in] to reduce contact pressure from the valve spring.

Description	New Part Number	Old Part Number
Valve Rotator	3640315	3081081

Note : It is recommended to install new valve springs and collets when replacing old-style rotators with new-style rotators.

The new rotators were structured into new cylinder head part numbers. The related part number changes are described in Table 1.

The new rotator was made available for service on 16-January-2008. The new rotator was implemented at Cummins Industrial Center on 11-February-2008. The ESN first for Daventry built engines is 33173180, which was built on 31-March-2008. The ESN first for India built engines is 25334936, which was built on 09-July-2008.

Table 1, Cylinder Head	
New Part Number	Old Part Number
3640316	3630361
3640317	3634259
3640318	3639978
3640319	3639979
3640320	3639984

Table 1, Cylinder Head	
New Part Number	Old Part Number
3640321	3811985
3640322	3811986
3640323	3811987
3640324	4099016
3640327	4924458
3640328	4959357
3640329	4959646
3640330	4963963