



Technical Service Bulletin

Technical Service Bulletin: tsb101011

Released Date: 17-Nov-2009

Oil Observed in Weep Hole of Service Fuel Pump

Oil Observed in Weep Hole of Service Fuel Pump

Core Issue

The purpose of this Early Field Notification is to highlight what appears to be an oil leak from the weep hole on replacement fuel pumps for QSK MCRS engines.

Confirmation

QSK19, QSK38, QSK50, and QSK60 engines with MCRS fuel systems and a service fuel pump installed:

Engine	Part Number
QSK19 MCRS	4998820
QSK38 MCRS	4998821
QSK50/60 MCRS	4998822
QSK60 MCRS Power Gen	2881161 **Release date and engine serial number (ESN) First to be determined.

Reports have been received that some fuel pumps have developed what appears to be an oil leak at the weep hole of the fuel pump. These leaks have been at extremely low hours, usually when the engine reaches operating temperature for the first time following service fuel pump installation.

If an engine with a service fuel pump appears to have an oil leak from the weep hole at extremely low hours or as the engine reaches operating temperature for the first time with a service fuel pump installed, it is likely that the cause identified below is the source of the complaint.

Pumps showing this symptom have been returned to the supplier and found to be properly assembled with no operational issues. The root cause of this leak has been determined to be residual assembly lubricant melting and exiting the assembly through the weep hole. When these pumps are tested at the supplier, they are tested with the lubricating oil at a cooler temperature than that of nominal engine operating temperature. Therefore, when the engine reaches operating temperature for the first time following service fuel pump installation, some residual assembly lubricant is heated and liquefied, the result of which appears to be engine oil leaking from the fuel pump weep hole.

None.

Resolution

The pump should be free of residual assembly lubricant within the first 1-2 hours of engine operation at normal operating temperature. If this condition is witnessed, clean the weep hole and fuel pump thoroughly. Inspect for a leak again after 2 hours of operation. If the leak has stopped, then no fix is necessary. If the leak continues, the fuel pump **must** be replaced.

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Last Modified: 17-Nov-2009
