



Technical Service Bulletin

Technical Service Bulletin: TSB110232

Released Date: 28-Sep-2011

QST30 Revised Industrial Fan Belt Tensioner

QST30 Revised Industrial Fan Belt Tensioner

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This document announces changes to the industrial fan belt tensioner for the QST30 engine. Former QST30 fan belt tensioner arrangements are explained in TSB 110003 and TSB 100650.

The new fan belt tensioner, Part Number 2888890, replaces fan belt tensioner, Part Number 4068467. The new fan belt tensioner has a control rod retainer with an o-ring groove and an o-ring, Part Number 43463 A. The revised control rod retainer assembly, Part Number 2888795, is better able to seal out liquid from the fan belt tensioner assembly.

Table 1. Revised QST30 Fan Belt Tensioner Assembly

New Part Number	Part Name	Old Part Number
2888890	Tensioner, Belt	4068467

The revised fan belt tensioner assembly, Part Number 2888890, is shown in Table 2. The assembly process utilizes Lubriplate™ 105, Part Number 3163087, or equivalent, to grease the internal components of the tensioner. This change began on 01-Aug-2011 with engine serial number (ESN) first 37250445.

Table 2. Contents of Revised Industrial QST30 Fan Belt Tensioner Assembly Part Number 2888890

Assembly Part Numbers	Sub-Assembly Part Numbers	Quantity	Part Name
S 253		1	Nut, Regular Hexagon Jam
S 500		1	Pin, Cotter
177269		1	End, Control Rod
2888795		1	Retainer, Control Rod
	2888794	1	Retainer, Control Rod
	43463 A	1	Seal, O-ring
3036900		1	Washer, Plain

Table 2. Contents of Revised Industrial QST30 Fan Belt Tensioner Assembly Part Number 2888890

Assembly Part Numbers	Sub-Assembly Part Numbers	Quantity	Part Name
3076301		2	Clamp, Wire Tie
3086244		1	Housing, Belt Tensioner
	3086245	1	Piece
	3086246	1	Piece
	3086247	1	Piece
3086251		1	Retainer, Spring
3086252		1	Pin, Clevis
3086253		1	End, Control Rod
3086269		1	Spring, Compression
3090194		1	Seal, Dust
3402156		1	Guide, Spring
4068466		1	Screw, Hexagon Head Cap

Use the following procedure in Service Manual, QST30 , Bulletin 4021539 for fan belt tensioner assembly information. Refer to Procedure 008-087 in Section 8.
 (/qs3/pubsys2/xml/en/procedures/57/57-008-087-tr.html)

This design change is for design improvement **only** and has no effect on warranty. If the fan belt is found seized on a QST30 engine, replace the fan belt tensioner with this revised design.

Document History

Date	Details
2011-8-3	Module Created

Last Modified: 28-Sep-2011
