



Technical Service Bulletin

Technical Service Bulletin: TSB120296

Released Date: 11-Dec-2012

QSK19/38/50/60 Modular Common Rail System (MCRS) Engine Data Link Throttle Unresponsive

QSK19/38/50/60 Modular Common Rail System (MCRS) Engine Data Link Throttle Unresponsive

Core Issue

After an engine replacement or upgrade from a CM850 to a CM2150, the engine may run normally at idle, but be unresponsive to the data link throttle's TSC1 message. This is due to the original equipment manufacturer (OEM) throttle message **not** meeting the Society of Automotive Engineers (SAE) J1939-71 standard.

Confirmation

The CM2150 module will **only** accept throttle messages (TSC1) that meet SAE J1939-71 standard. The CM850 module would accept messages that were very close, but **not** identical, to the SAE J1939-71 standard.

TSC1 Message Format Examples	
Correct TSC1 Message Format Example	Incorrect TSC1 Message Format Example
xx0000xx AA BB BB CC 00 00 DD EE	xx0000xx AA BB BB CC 00 00 00 00

AA = Control Mode (i.e. Speed Command/Speed Limit)

BB = Speed Command Value/Limit

CC = Torque Value/Limit

DD = Message Counter (**Must be 0xF if not used**)

EE = Checksum (**Must be 0xF if not used**)

Resolution

Reference the original equipment manufacturer (OEM) troubleshooting or technical service bulletins for information on how to update their software to meet SAE J1939-71 standards.

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Document History

Date	Details
2012-11-26	Module Created

Last Modified: 11-Dec-2012
