



Technical Service Bulletin: TSB130062

Released Date: 22-May-2013

QST30 Industrial LTA Water Pump Shaft Material Improvement

QST30 Industrial LTA Water Pump Shaft Material Improvement

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This document announces a product improvement for the QST30 Industrial LTA water pump and the auxiliary drive on the front left bank of the engine. The new parts are backward compatible with the existing part numbers.

The improvement made to the LTA pump was a material change from 431 stainless steel to heat treated 4140 steel.

The auxiliary drive dimensions remain the same, with the exception of an increased spline length. The previous drive spline length was 22 mm [0.866 in]. The new drive spline length is 32.5 mm [1.280 in].

Excessive wear and spline malfunctions have been seen on some QST30 Industrial haul truck applications on certain original equipment manufacturers (OEMs). These malfunctions have **not** been seen on drill rigs, frac rigs, or other applications that do **not** see transient loads like the haul truck applications. The parts were screened and inspected to be within the proper Cummins specification. It was determined that this was **not** a quality issue with the spline material, but an application and site specific issue.

The existing stock of the pump and drive will be obsoleted and superseded. When replacing an LTA water pump, it is recommended to use the new part number on haul trucks and other applications that see transient loads.

- Engine serial number (ESN) First: 37258087
- Date: 13-May-2013

Table 1. New and Old Pump and Drive

Part Name	New Part Number	Old Part Number
LTA Water Pump	4310976	4068463
Auxiliary Drive	4310977	4068492

Document History

Date	Details
2013-3-26	Module Created

Last Modified: 22-May-2013
