



Technical Service Bulletin

Technical Service Bulletin: TSB130131

Released Date: 04-Oct-2024

Possible Communication Issue with the INLINE™ 6 9-pin Connector Cable During Data Monitor Logging (DML)

Possible Communication Issue with the INLINE™ 6 9-pin Connector Cable During Data Monitor Logging (DML)

Core Issue

There is a possible communication issue with the INLINE™ 6 9-pin connector cable during Data Monitor Logging (DML), if pins H and J are connected to something other than a CAN network.

All 9-pins of the INLINE™ 6 connector cable are used. Therefore, if an original equipment manufacturer (OEM) decides to use pins H and J for something other than a CAN network, it may interfere with the INLINE 6 CAN circuitry. More specifically, connection is lost during DML logging and error 5201 is encountered.

Confirmation

N/A

Resolution

As the chart below illustrates, no issues are encountered when an INLINE™ 5 9-pin connector cable is used, regardless of the adapter type. However, the CAN 2 network capability will be lost when an INLINE™ 5 9-pin connector cable is used with the INLINE™ 6 data link adapter. The communication issue may **only** be encountered when the INLINE™ 6 9-pin connector cable is used in combination with the INLINE™ 6 data link adapter. Although Cummins Inc. no longer sells the INLINE™ 5 kit, the INLINE™ 5 9-pin connector cable can still be purchased separately under the Part Number 3165159.

Adapter Type	9-pin Connector Cable Type	Result
INLINE™ 6	INLINE™ 6 9-pin connector cable	Issue
INLINE™ 6	INLINE™ 5 9-pin connector cable	No issue
INLINE™ 5	INLINE™ 5 9-pin connector cable	No issue

Adapter Type	9-pin Connector Cable Type	Result
INLINE™ 5	INLINE™ 6 9-pin connector cable	No issue

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Document History

Date	Details
2013-8-28	Module Created
2017-1-13	Quick Fix application: did not change content of the file. Testing Quick fix application
2017-6-8	Quick Fix application:
2017-7-7	Non-Product Problem Solving (PPS). Fixing an outfile.
2024-10-4	Checking TSB contents, no changes made.

Last Modified: 04-Oct-2024
