



Technical Service Bulletin

Technical Service Bulletin: TSB140102

Released Date: 11-Aug-2014

New Head Gaskets for 19, 38, and 50 Liter Engines

New Head Gaskets for 19, 38, and 50 Liter Engines

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This document introduces new head gaskets for the 19, 38, and 50 liter engines.

The purpose of this change is to improve sealing capability of the head gaskets in conditions where certain chemical incompatibilities exist between the engine fluids and the grommet material. The grommets were previously made from silicone for both coolant and oil.

Some organic acid technology (OAT) coolants used do **not** meet CES 14603 and **must** be treated by adding .24 liter [8 oz] of liquid silicate fluid for every 45 liters [12 gal] of total coolant system volume. It is critical to **not** overtreat the coolant with silicate fluid. If overtreatment is suspected, drain the cooling system and discard the filter. Clean the cooling system immediately. These coolants have been shown to attack the silicone in the head gasket grommets. Refer to Service Bulletin, 3666132 (/qs3/pubsys2/xml/en/bulletin/3666132.html) for further information.

This change will be made in production for the K38, K50, QSK38, and QSK50 engines that originate from the Daventry Engine Plant. The K and QSK19 engines will **not** change head gaskets in production at this time.

All service head gaskets for these engines will move to the new part numbers.

There is no change to the installation or removal procedure due to these changes.

Table 1 lists the new and old part numbers.

Table 1: Head Gasket Part Numbers

Description	New Part Number	Old Part Number
Standard	4334080	3634664
Oversize	4334081	3634788

Document History

Date	Details
2014-8-5	Module Created

Last Modified: 11-Aug-2014
