



Technical Service Bulletin

Technical Service Bulletin: TSB150151

Released Date: 21-Jan-2016

New Oil Level Sensor

New Oil Level Sensor

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- QSK38
- QSK45 CM500
- QSK45 G
- QSK50 CM850
- QSK50 CM2150 MCRS
- QSK50 DF CM850/CM2150 MCRS
- QSK50 CM2150 K107
- QSK50 CM2350 K108
- QSK60 CM500
- QSK60 CM850 MCRS
- QSK60 CM2150 MCRS
- QSK60 G
- QSK78 CM500
- QSK78 CM2250 K104
- QKS78 PG CM500 and CM850

Description of Change

This document announces the release of a new oil level sensor. The new oil level sensor, Part Number 4358900, includes a hard convolute attached to a hardened backshell. A heat shrink seal has replaced the existing oil level sensor nylon dust guard and will help to increase the connector robustness against foreign material and moisture intrusion.

Reason for Change

The oil level sensor was improved to prevent foreign material and moisture ingress into the backshell of the connector. Foreign material and moisture can cause a change in resistance between pins, which causes erratic signal and false readings. Fault Codes 471, 252, 219, 141, 147, 232, 422, and 729 can become active.

Service Parts Availability

Table 1, Service Parts

Part Description	Obsolete Part Number	New Part Number
Oil Level Sensor	3408653	4358900

Part Identification

The new oil level sensor can be identified by a hard convolute/corrugated tube attached to a hardened backshell connector.

Part Structure

The previous oil level sensor, Part Number 3408653, has been obsoleted and superseded by the new oil level sensor, Part Number 4358900.

Part Inventory Action

None.

Production Status

Implemented for production. See Table 2.

Table 2, Production Information

Product	ESN First	Build Date *	Engine Plant
QSK78 CM500	66303676	1 September 15	Daventry
QSK60 CM500	33205636	1 September 15	Daventry

*Engine build date can be found on the engine dataplate.

Document History

Date	Details
2015-9-11	Module Created
2016-1-21	Removed engines from product affected that do not utilize the new oil level sensor. Added QKS78 PG CM500 and CM850 to Product Affected.

Last Modified: 21-Jan-2016
