



Technical Service Bulletin

Technical Service Bulletin: TSB150193

Released Date: 28-Jan-2016

Fault Code 6719 Engine Will Not Crank

Fault Code 6719 Engine Will Not Crank

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- QSK19 CM2150 MCRS
- QSK38 CM2150 MCRS
- QSK50 CM2150 MCRS
- QSK60 CM2150 MCRS

Issue

Customers may encounter a no crank no start condition after STOP ENGINE lamp (red lamp) illuminates for most severe Fault Code 6719.

Certain Original Equipment Manufacturer (OEM) application interfaces will **not** enable cranking if a STOP ENGINE lamp is active. In the ECM calibration codes listed in Table 1 below, Fault Code 6719, which causes the STOP ENGINE lamp, is **not** able to be cleared with ECM power cycle if engine cranking is **not** enabled.

Least severe Fault Code 2261 and moderately severe Fault Code 2216 also active for fuel pump supply pressure signify a fuel quality issue and rising Stage 2 fuel filter restriction.

In order for the Fault Codes to clear without using INSITE™ electronic service tool, three things **must** be satisfied:

1. Engine Control Module (ECM) Power Cycle (key off for 30 seconds)
2. Stage 2 Fuel Pressure Sensor measures below threshold of 1400 kPa [203 psi]
3. Engine rpm is above 600 rpm.

Verification

Applications that do **not** enable cranking with an active STOP ENGINE lamp will be affected if the following is true:

1. ECM has ECM calibration code from Table 1 below
2. Stage 2 fuel filter plugging is generating Fault Code 6719

3. Application/OEM will **not** engage starter until STOP ENGINE lamp is turned off when Fault Code 6719 goes inactive
4. Engine ECM power down completed in attempt to clear Fault Code and restart engine

Table 1, Affected ECM Calibration Codes

AQ60479.04	AQ60294.07	AQ60376.09	AQ60371.10	AQ60691.05
AQ60217.15	AQ60458.05	AQ60377.10	AQ60416.07	AQ60694.03
AQ60252.10	AQ60489.03	AQ60378.11	AQ60441.09	AQ60677.03
AQ60296.08	AQ60492.04	AQ60379.10	AQ60455.08	
AQ60320.08	AQ60301.09	AQ60380.10	AQ60361.10	
AQ60484.04	AQ60493.05	AQ60381.10	AQ60363.12	
AQ60504.04	AQ60421.07	AQ60386.11	AQ60364.10	
AQ60701.02	AQ60498.04	AQ60395.11	AQ60365.10	
AQ60399.11	AQ60429.07	AQ60404.11	AQ60387.13	
AQ60401.10	AQ60500.04	AQ60445.07	AQ60388.10	
AQ60420.06	AQ60297.06	AQ60476.07	AQ60389.10	
AQ60490.07	AQ60309.08	AQ60690.02	AQ60390.10	
AQ60220.15	AQ60310.08	AQ60695.03	AQ60391.12	
AQ60338.11	AQ60444.06	AQ60696.03	AQ60392.08	
AQ60293.07	AQ60463.05	AQ60696.03	AQ60397.09	
AQ60491.04	AQ60464.06	AQ60700.04	AQ60402.10	
AQ60287.10	AQ60453.08	AQ60751.00	AQ60410.09	
AQ60480.04	AQ60359.11	AQ60454.08	AQ60440.08	
AQ60288.10	AQ60362.10	AQ60360.10	AQ60442.07	
AQ60481.05	AQ60366.10	AQ60367.10	AQ60443.11	
AQ60289.12	AQ60373.12	AQ60368.10	AQ60456.08	
AQ60417.08	AQ60374.10	AQ60369.10	AQ60475.08	
AQ60292.07	AQ60375.10	AQ60370.10	AQ60499.06	

Resolution

New ECM calibration codes are available that resolve the no crank no start condition caused by Fault Code 6719 coming active.

- Install the latest ECM calibration code.
 - The new ECM calibration codes can be identified by being at least one revision level higher than the affected calibrations listed in Table 1 above.
- Address the root cause of fuel filter plugging after fuel inlet restriction is verified.
 - See the corresponding Service Manual. Reference Procedure 006-020 in Section 6.

Fault Code 4615 has replaced Fault Code 6719 in the new ECM calibration codes.

The theory of operation for Fault Code 2261, 2216, and 4615 with the new ECM calibration codes can be found in Table 2 below.

Table 2, Fault Code Theory of Operation					
Fault Code	Lamp Type	Latching	Engine Derate	Condition for Activation	Conditions for Clearing
2261	Maintenance	No	No	Fuel supply pressure is above 1000 kPa [145 psi]	Fuel supply pressure below 1000 kPa [145 psi]
2216	Amber Warning	Yes	No	Fuel supply pressure is above 1200 kPa [174 psi]	Powering down the ECM followed by engine speed above 600 rpm and fuel supply pressure below 1200 kPa [174 psi]
4615	Amber Warning	Yes	1400 rpm	Fuel supply pressure is above 1400 kPa [203 psi]	Powering down the ECM followed by engine speed above 600 rpm and fuel supply pressure below 1400 kPa [203 psi]

Document History

Date	Details
2015-12-14	Module Created

Last Modified: 28-Jan-2016
