



Technical Service Bulletin: TSB160115

Released Date: 01-Dec-2016

New Low Temperature Aftercooler (LTA) Thermostat

New Low Temperature Aftercooler (LTA) Thermostat

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- QSK38 CM2150 MCRS
- QSK38 CM2358 K112
- QSK38 CM850 MCRS
- QSK45 CM500
- QSK45 G
- QSK50 CM2150 K107
- QSK50 CM2150 K108
- QSK50 CM2150 MCRS
- QSK50 CM850 MCRS
- QSK50 DF CM850/CM2150 MCRS
- QSK60 CM2150 MCRS
- QSK60 CM2250 K112
- QSK60 CM2350 K116
- QSK60 CM2350 K117
- QSK60 CM2358 K110
- QSK60 CM850 MCRS
- QSK60 G
- QSK78 CM500
- QSK78 CM2250 K104
- QSK78 CM850
- QSK78 PG CM500
- QSK78 PG CM850
- QSK95 CM2350 K111
- QSK95 CM2350 K113

Issue

Symptom:

- Improperly high or low intake manifold charge air temperature.

Root Cause:

- Rubber plunger in low temperature aftercooler (LTA) thermostat degrades and breaks up, causing LTA thermostat to stick and seize.
- Rubber plunger in LTA thermostat degrades and causes secondary damage to LTA thermostat diaphragm.

Verification

- Verify LTA thermostat has seized in the open position by visually inspecting LTA thermostat. For removal information, see corresponding Service Manual or Troubleshooting and Repair Manual. Reference Procedure 008-013 in Section 8.
- If LTA thermostat is closed, suspend LTA thermostat in container of heated water. See LTA thermostat Test section in corresponding Service Manual or Troubleshooting and Repair Manual. Reference Procedure 008-013 in Section 8.

Resolution

- Replace existing LTA thermostat with new LTA thermostat. See Table 1 below. See corresponding Service Manual or Troubleshooting and Repair Manual. Reference Procedure 008-013 in Section 8.
- New LTA thermostat has improved rubber compound and wiper seal to address both malfunction modes.

Service Parts Availability

Service parts are available. See Table 1 for part numbers.

Table 1, Service Parts				
Part Description	Existing Part Number	Obsoleted	Superseded	New Part Number
Thermostat	4065566	Yes	Yes	3651379

Production Status

Implemented for production. See Table 2.

Table 2, Production Information			
Product	ESN First	Build Date ¹	Plant
QSK60 CM2150 MCRS	33206899	22-February-2016	Daventry Engine Plant
QSK78 CM500	66303820	22-February-2016	Daventry Engine Plant

¹Engine build date can be found on the engine dataplate.

Document History

Date	Details
2016-10-27	Module Created

Last Modified: 01-Dec-2016
