



Technical Service Bulletin

Technical Service Bulletin: TSB180082

Released Date: 02-Sep-2024

New Dual Impeller Water Pump

New Dual Impeller Water Pump

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- KTA50
- QSK38
- QSK38 CM2150 K106
- QSK50 CM850
- QSK50 CM2150 MCRS
- QSK50 CM2150 K107
- QSK50 CM2350 K108
- QSK50 CM2350 K130
- QSK60 CM500
- QSK60 CM850
- QSK60 CM2150
- QSK60 CM2250 K112
- QSK60 CM2350 K116
- QSK60 CM2350 K117
- QSK60 CM2350 K121
- QSK60 CM2350 K135
- QSK60 CM2350 K136

Description of Change

This document announces the release of a new dual impeller water pump with revised oil supply orifices on the 38 L and 50 L models and a more robust spring loaded rubber oil seal to improve sealing on both the 38 L, 50 L and 60 L models.

Reason for Change

Existing water pump may show signs of oil and coolant at weep hole. Existing orifice sizes can allow for high oil levels in bearing housing. Existing seal can show premature wear because of less robust PTFE material.

Service Instructions

See the following Service Manuals and reference Procedure 008-062 in Section 8:

- GTA38, K38, K50, QSK38 and QSK50 Service Manual, Bulletin 4021528
- K117 Service Manual, Bulletin 4367449
- K121 Service Manual, Bulletin 4388645
- K135 Service Manual, Bulletin 5504626
- K136 Service Manual, Bulletin 5504631
- QSK38 CM2150 K106 Service Manual, Bulletin 4332768
- QSK45 and QSK60 Service Manual, Bulletin 4021530
- QSK60 CM2250 K112 Service Manual, Bulletin 4367454
- QSK60 CM2350 K116 Service Manual, Bulletin 4367444

Service Parts Availability

Service parts are available. See Table 1 for part numbers. **Only** kit part numbers are available to purchase for service.

Table 1, Service Parts

Part Description	Existing Part Number	Obsolete	Superseded	New Part Number	ReCon® Part Number
PUMP, WATER (50 L)	3651198/36 51200	Yes	Yes	5376264	-
KIT, WATER PUMP (50 L)	-	-	-	5473148	5473148RX
PUMP, WATER (60 L)	4085944/36 51206	Yes	Yes	5375545	-
KIT, WATER PUMP (60 L)	-	-	-	5579320	5579320RX
PUMP, WATER (QSK38 T2 Bear)	3649111	Yes	Yes	5611546	-
KIT, WATER PUMP (QSK38 T2 Bear)	-	-	-	5633388	5633388RX
PUMP, WATER (QSKTA38)	3651202	Yes	Yes	5611547	-
KIT, WATER PUMP (QSKTA38)	-	-	-	5633387	5633387RX

Note : Part description 'PUMP, WATER' is the water pump with the drive gear installed. Part description is the water with the drive gear installed, plus all necessary gaskets and o-rings, etc.

Part Inventory Action

Use existing part number inventory before using the new part number.

Production Status

Implemented for production. See Table 2.

Table 2, Production Information

ESN First	Build Date ¹	Plant
33212948 (QSK50)	12 February 2018	Daventry Plant SO10211
33220103 (QSK60 T4)	14 October 2019	Daventry Plant SO11236
33221345 (QSK60 T2)	23 March 2020	Daventry Plant SO11861/1
33221364 (KTA50)	25 March 2020	Daventry Plant SO11143/9
33222011 (QSKTA 38)	26 June 2020	Daventry Plant SO10094
33222032 (QSK38 Bear T2)	29 June 2020	Daventry Plant SO65921
33210550 (QSK38 CM2150 K106)	18 July 2017	Daventry Plant

¹Engine build date can be found on the engine dataplate.

Document History

Date	Details
2018-6-12	Module Created
2018-7-16	Added QSK50 CM850 to Product Affected section.
2019-12-13	Added necessary products to Product Affected section, added to Bulletins to Service Instructions, and added Product Information to both Tables.
2020-3-18	Corrected part numbers listed in Table 1 for the QSK50 water pump and QSK60 T4 water pump.
2020-5-27	Added necessary products to Product Affected section, and corrected Tables 1 and 2.
2020-7-13	Added QSK38 to Product Affected section. Corrected Tables 1 and 2.
2020-8-3	Added relevant part numbers to table.
2021-5-24	Added QSK38 CM2150 K106
2021-6-10	Part number 5376264 corrected to 5375545.

Date	Details
2022-3-9	Updated Table 1.
2024-7-10	Updated Table 1.

Last Modified: 02-Sep-2024
