



Technical Service Bulletin

Technical Service Bulletin: TSB190056

Released Date: 30-Apr-2019

New Engine Air Starting Motor

New Engine Air Starting Motor

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- G50
- GTA38
- K38
- K50
- K50-DPM
- KTA38GC CM558
- QSK38 CM2150 K106
- QSK38 CM2150 MCRS
- QSK38 CM850 MCRS
- QSK45 CM500
- QSK50 CM2150 K107
- QSK50 CM2150 MCRS
- QSK50 CM2350 K108
- QSK50 CM850 MCRS
- QSK50 DF CM850/CM2150 MCRS
- QSK60 CM2150 MCRS
- QSK60 CM2250 K112
- QSK60 CM2350 K116
- QSK60 CM2350 K117
- QSK60 CM2350 K121
- QSK60 CM2350 K133
- QSK60 CM500
- QSK60 CM850 MCRS
- QSK60 G
- QSK60 G CM2358 K110

Description of Change

A new engine air starting motor has been released with a more robust pinion tooth chamfer design.

Reason for Change

Existing engine air starting motors may not engage with the flywheel on the initial attempt to start, causing a crank failure fault on the diesel control unit and preventing further starting attempts.

Service Parts Availability

Service parts are available. See Table 1 for part numbers.

Table 1, Service Parts				
Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
MOTOR, STARTING	3634784	Yes	Yes	5544765
MOTOR, STARTING	4100563	Yes	Yes	5544766
MOTOR, STARTING	4100562	Yes	No	-

Document History

Date	Details
2019-4-12	Module Created