



Technical Service Bulletin: TSB190169

Released Date: 01-Oct-2019

Low Engine Hour False Lubricating Oil Pan Leaks

Low Engine Hour False Lubricating Oil Pan Leaks

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- QSK50 (All Versions)
- QSK60 (All Versions)
- QSK78 (All Versions)

Issue

Symptom:

- Lubricating oil pan to adaptor joint appears to be leaking fluid or lubricating oil on low hour engines.

Root Cause:

- Assembly grease is applied to the lubricating oil pan rail before the lubricating oil pan and gasket are installed, this is the source of the fluid that has been mistaken for engine lubricating oil leaks.

Verification

- If a lubricating oil leak is suspected, see corresponding Service Manual or Troubleshooting and Repair Manual. Reference Procedure 007-024 in Section 7.
- Adding dye to the lubricating oil and performing a florescent dye tracer test will reveal if the fluid is engine lubricating oil or assembly grease. Lubricating oil is confirmed **only** if dye is visible after performing the florescent dye tracer test.

Resolution

- Clean the assembly grease streaks from the engine. The assembly grease will bake off in time with normal engine operation.

Document History

Date	Details
2019-9-26	Module Created

Last Modified: 01-Oct-2019
