



Technical Service Bulletin

Technical Service Bulletin: TSB200236

Released Date: 03-Sep-2025

New Valve Spring

New Valve Spring

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- K19 (All Versions)
- K19G (All Versions)
- K38 (All Versions)
- K50 (All Versions)
- KTA19 (All Versions)
- KTA38 (All Versions)
- KTA50 (All Versions)
- QSK19 (All Versions)
- QSK19G (All Versions)
- QSK19N (All Versions)
- QSK38 (All Versions)
- QSK50 (All Versions)

Description of Change

This TSB Replaces TSB120148 and does **not** apply to K19, KTA19, QSK19 horizontal rail engines, as these engines use a different cylinder head. New valve spring part number and cylinder head part numbers have been released for ReCon® and Service. The new spring will be made available as an individual component or included as part of a full cylinder head assembly.

Reason for Change

New valve spring part number and cylinder head part numbers have been released for ReCon® and Service.

Customer Communication

- Follow existing QuickServe® Online (QSOL) procedures for changing valve springs or cylinder heads.
- New valve springs contain damping coils making them visibly different in form to the old valve spring.

- New valve springs have a yellow orientation instruction and arrow printed on the spring itself.

Service Instructions

- Follow existing QSOL procedures for changing valve springs or cylinder heads.
- New valve springs contain damping coils making them visibly different in form to the existing valve spring.
- New valve springs have a yellow orientation instruction and arrow printed on the spring itself.

Service Parts Availability

Service parts are available. See Table 1 for part numbers.

Table 1, Service Parts					
Part Description	Existing Part Number	Obsolete	Superseded	New Part Number	New Part Number (ReCon®)
SPRING, VALVE	3643725	No	No	5559727	-
HEAD, CYLINDER	3646310	Yes	Yes	5581139	5581139RX
HEAD, CYLINDER	3646323	Yes	Yes	5581141	5581141RX
HEAD, CYLINDER	3646328	Yes	Yes	5581142	5581142RX
HEAD, CYLINDER	3646329	Yes	Yes	5581143	5581143RX
HEAD, CYLINDER	3649935	Yes	Yes	5581144	5581144RX
HEAD, CYLINDER	4072649	Yes	Yes	5581145	5581145RX
HEAD, CYLINDER	4313887	Yes	Yes	5581146	5581146RX
HEAD, CYLINDER	4350445	Yes	Yes	5581147	5581147RX
HEAD, CYLINDER	4381497	Yes	Yes	5581148	5581148RX
HEAD, CYLINDER	4396709	Yes	Yes	5581149	5581149RX

Part Compatibility

Full compatibility, the new valve spring will fit the existing part number cylinder heads.

Part Identification

- New valves springs are identified with yellow orientation arrow and instruction 'TOP'. This is printed onto the valve spring.
- New valve springs are visibly different to the existing part number valve spring due to the addition of damping coils which are to be orientated cylinder head side of the assembly.
- Complete functionality of the valve spring will be lost if **not** orientated correctly.



Figure 1, New Valve Spring Installed on Cylinder Head with Correct Orientation.

Part Inventory Action

Use existing part number inventory before using the new part number.

Product Status

New factory-built engines are being implemented by Option Numbers with a staggered implementation to avoid disruption to the supply chains.

Table 2, Production Information

Option Number	Implementation Date	Plant
Table 1 Items	20 August 2020	PDC (Global)
PP43380 PP43379 PP43548 PP43905	22 May 2023	Daventry
PP44261 PP44340 PP44806	8 September 2025	Daventry

Document History

Date	Details
2020-12-4	Module Created
2021-2-17	Added necessary note to TSB content.
2022-1-19	Updated Table 1.
2022-3-15	Updated Description of Change and Reason for Change to include statement about new valve spring part number and
2023-10-19	Added Table 2 and Table 3.
2025-9-3	Updated Table 1 and Table 2.