



Technical Service Bulletin

Technical Service Bulletin: TSB210141

Released Date: 04-Aug-2021

Oil Transfer Connection Gasket Part Number and Material Change

Oil Transfer Connection Gasket Part Number and Material Change

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- GTA38
- K38
- K38 CM558
- K50
- K50 Natural Gas
- QSK38 (All Versions)
- QSK50 CM2150 DEMU
- QSK50 CM2150 K140M
- QSK50 CM2150 MCRS
- QSK50 CM2350 K108
- QSK50 CM2350 K108
- QSK50 CM2350 K130
- QSK50 CM2350 K130
- QSK50 CM2350 K146G
- QSK50 CM850 MCRS
- QSK50 DF CM850/CM2150 MCRS

Description of Change

- The existing rubber oil transfer connection gasket is being replaced by a laminated steel and rubber version.
- The new oil transfer connection gasket will feature an embossed face for improved sealing and a part number change.

Reason for Change

- The existing rubber oil transfer connection gasket disintegrated because of the loading of the long thin walls around the transfer port bore under the rising and falling of engine lubricating

oil pressures.

- The new laminated steel and rubber oil transfer connection gasket has a steel lamination to support the thin walls and reduce movement due to the rising and falling of engine lubricating oil pressures.

Service Instructions

- Use new part number communicated in Table 1 below.
- There is an embossed face to the oil transfer connection gasket that **must** be fitted to the mounting face of the oil transfer block.

Service Parts Availability

Service parts are available. See Table 1 for part numbers.

Table 1, Service Parts

Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
CONNECTION, GASKET	3000632	Yes	Yes	5542669

Part Identification

The new gasket has an embossed seal which is **not** present on the existing part.

Part Inventory Action

Obsolete part numbers in stock are not to be used. Obsolete part numbers in stock are to be returned for reimbursement.

Production Status

Implemented for production. See Table 2.

Table 2, Production Information

ESN First	Build Date ¹	Plant
33224647	30 April 2021	Daventry/KCL/CCEC

¹Engine build date can be found on the engine dataplate.

Publications Affected

Table 3, Publications Affected

Manual Type	Engine	Bulletin Number	Procedure Title	Procedure	Section
Service Manual	GTA38, K38, K50, QSK38, QSK50	4021528	Lubricating Oil Transfer Tube	Refer to Procedure 007-040 (/qs3/pubsys2/xml/en/procedures/28/28-007-040-tr.html)	7

Table 3, Publications Affected					
Manual Type	Engine	Bulletin Number	Procedure Title	Procedure	Section
Service Manual	QSK50 CM2350 K108	4332823	Lubricating Oil Transfer Tube	Refer to Procedure 007-040 (/qs3/pubsy s2/xml/en/pr ocedures/25 5/255-007-040-tr.html)	7
Service Manual	QSK50 CM2350 K130	5504180	Lubricating Oil Transfer Tube	Refer to Procedure 007-040 (/qs3/pubsy s2/xml/en/pr ocedures/53 6/536-007-040-tr.html)	7
Service Manual	GTA38, K38, K50, QSK38, QSK50	4021528	Oil Transfer Connection	Refer to Procedure 007-061 (/qs3/pubsy s2/xml/en/pr ocedures/28 /28-007-061-tr.html)	7
Service Manual	QSK50 CM2350 K108	4332823	Oil Transfer Connection	Refer to Procedure 007-061 (/qs3/pubsy s2/xml/en/pr ocedures/25 5/255-007-061-tr.html)	7
Service Manual	QSK50 CM2350 K130	5504180	Oil Transfer Connection	Refer to Procedure 007-061 (/qs3/pubsy s2/xml/en/pr ocedures/53 6/536-007-061-tr.html)	7

Document History

Date	Details
2021-6-29	Module Created

Last Modified: 04-Aug-2021
