



Technical Service Bulletin: TSB210149

Released Date: 29-Oct-2021

New Rocker Housing Gasket Design: External Oil Leaks, Oil Consumption, or Low Oil Pressure

## New Rocker Housing Gasket Design: External Oil Leaks, Oil Consumption, or Low Oil Pressure

### Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

### Contents

#### Product Affected

- QST30 CM552
- QST30 CM850

#### Issue Summary

Symptoms:

- External oil leaks from components such rocker lever housing to cylinder head mounting surface
- Conditions of high oil consumption and or readings may show lubricating oil pressure low

Root Cause:

- Existing design can deteriorate with temperatures exceeding design intent thresholds. Temperatures can increase based on harsher duty cycles which is dependent on application purposes.

#### Verification

Verify high oil consumption, low oil pressure, and or observation confirms rocker housing gasket allows oil seepage or dripping oil.

#### Resolution

Replace leaking rocker housing gasket with corresponding part numbers in Table 1 below.

#### Description of Change

New service gasket solution changes include:

- New gasket material has a reinforced carbon steel wire mesh for better stability.
- New gasket material has better engine temperature compatibility with all applications.

## Service Parts Availability

Service parts are available. See Table 1 below for part numbers.

**Table 1, Service Parts**

| Part Description                                                                | Existing Part Number | Obsolete | Superseded | New Part Number |
|---------------------------------------------------------------------------------|----------------------|----------|------------|-----------------|
| Gasket, Rocker Housing                                                          | 4975638              | Yes      | Yes        | 3092480         |
| Gasket, Rocker Housing<br>Komatsu Design<br>(New Intermediate Service Solution) | 3092480              | No       | No         | -               |

### Part Inventory Action

- If customer and or distributor order requests for new intermediate service solution part number, release and grant order.
- If the customer and or distributor order requests for existing part number, continue to honor those orders. Future production gasket will supersede and obsolete the existing gasket once available.

## Document History

| Date       | Details                           |
|------------|-----------------------------------|
| 2021-7-8   | Module Created                    |
| 2021-10-26 | Non-Product Problem Solving (PPS) |

---

**Last Modified: 29-Oct-2021**

---