



Technical Service Bulletin: TSB210213

Released Date: 06-Oct-2021

Wire Harness Relay Mounting Improvements

Wire Harness Relay Mounting Improvements

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- QST30 CM552
- QST30 CM850

Issue Summary

Wire harness relay, Part Number 3658780, can become partially disconnected causing contact malfunction.

Symptom:

- Low Power or No Power

Root Cause:

- Relay contact malfunction

Resolution

- If wiring harness relay has already malfunctioned, replace the wiring harness relay. See corresponding Service Manual. Reference Section 019-211 in Section 19.
- Wire ties can be added to improve wiring harness relay support and prevent contact malfunction.
- Add quantity three of part number 3062329 as instructed:
 - Install one wire tie around two wiring harness relay halves (yellow tie), verify tie is routed under wiring harness relay boot.
 - Install second wire tie (blue tie) to wrap around wiring harness relay and bottom wire tie.
 - Install the last wire tie (red tie) around wiring harness relay and bottom wire tie and wiring harness. Reference Figure 1 below. Figure 2 shows production solution.



Figure 1, Wire Tie Placement on Wiring Harness Relay.



Figure 2, Production Solution on Wiring Harness Relay.

Date	Details
2021-10-6	Module Created

Last Modified: 06-Oct-2021
