



Technical Service Bulletin: TSB210256

Released Date: 18-Nov-2021

External Coolant Leak: Incorrect Lifting Bracket Capscrews

External Coolant Leak: Incorrect Lifting Bracket Capscrews

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

Engines:

- QST30 CM552
- QST30 CM850

ESN Build Date Range:

- 1 September 2021

Issue Summary

Symptom:

- Lifting bracket capscrews **not** fully seated
- External coolant Leak

Root Cause:

- Incorrect length capscrews installed
- Lifting bracket capscrews were incorrectly packaged and 50 mm capscrew were installed instead of the proper 45 mm capscrews.
- The longer capscrew can result in an inadequate final torque to the lifting bracket and a coolant leak.



Figure 1, QST30 Lifting Bracket With 6 Capscrews Shown.

Verification

- Engines are to be inspected to verify the lifting bracket capscrews are fully seated.



Figure 2, (1) Correct Capscrew, Part Number 3093754; (2) Incorrect Capscrew, Part Number 3093755; (3) Acceptable Substitute Capscrew, Part Number 3093940 .

Resolution

Correct length lifting bracket capscrews have been received at the engine manufacturing plant and are available through the local distributor.

Install proper length lifting bracket capscrews. See Table 1 below for part numbers.

Service Parts Availability

Service parts are available. See Table 1 for part numbers.

Table 1, Service Parts	
Part Description	Part Number
Incorrect 50 mm 10.9 capscrew	3093755
Correct 45 mm 10.9 capscrew	3093754
Substitution 45 mm 10.9 flange capscrew	3093940

Document History

Date	Details
2021-11-17	Module Created