



Technical Service Bulletin

Technical Service Bulletin: TSB210269

Released Date: 25-Aug-2022

Engine Will Not Crank or Cranks Slowly (Electric Starter): Debris and Dust in Electric Starting Motor

Engine Will Not Crank or Cranks Slowly (Electric Starter): Debris and Dust in Electric Starting Motor

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- QST30 CM2350 T101
- QST30 CM552
- QST30 CM850

Issue Summary

Symptom:

- Engine will **not** crank or cranks slowly (electric starter)

Root Cause:

- Nose bushing of electric starting motor contamination causing nose bushing and drive end bushing wear

Verification

Visual inspection of electric starting motor can confirm if dust and debris has collected in nose cone of electric starting motor where slow cranking or no cranking of the engine is experienced.

Resolution

- If dust and debris has collected in the nose cone of the electric starting motor, a noseless electric starting motor option is available. See Table 1 for part number information.
- For proper removal and install instructions, see corresponding QST30 Service Manual. Reference Procedure 013-020 in Section 13.

Service Parts

Table 1, Service Parts				
Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
Motor, Starting	3651893	No	No	4371902
Production Status				
Implemented for production. See Table 2.				
Table 2, Production Information				
ESN First		Build Date ¹	Plant	
37287882		July 2022	Seymour Engine Plant	
¹ Engine build date can be found on engine dataplate.				

Document History

Date	Details
2021-12-9	Module Created
2022-8-23	Added Production Status Section