



Technical Service Bulletin

Technical Service Bulletin: TSB230167

Released Date: 05-Sep-2023

Missing Rocker Lever Rivets

Missing Rocker Lever Rivets

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- KTAA19 K131G
- KTAA38 K134G
- KTA50 K148G
- QSK19 CM850 MCRS
- QSK19 CM2150 K139M
- QSK19 CM2350 K114
- QSK19 CM2350 K144G
- QSK19 CM2350 K167C
- QSK19 CM2450 K155G
- QSK38 CM850 MCRS
- QSK38 CM2150 K142M
- QSK38 CM2350 K125
- QSK38 CM2350 K138M
- QSK38 CM2350 K145G
- QSK50 CM2150 K140M
- QSK50 CM2150 MCRS
- QSK50 CM2150 MCRS G
- QSK50 CM2350 K146G
- QSK50 CM2350 K163C

Issue Summary

Symptom:

- Missing rivet at rocker lever cross drilling

Root Cause:

- Improper fit between rocker lever drilling inside diameter and rivet outside diameter

Verification

Verification is visual **only** and does **not** have to be proactive. During planned maintenance of the overhead, remove rocker lever cover and inspect rocker levers.

Resolution

- If a missing rivet is verified, options for replacement are available. The original rivet can be installed in existing rocker lever or rocker lever assembly can be replaced with a new part number with an improved plug. Plug design changed from a rivet to ball plug style. See Table 1 for part number details.
- Replacement of the rivet does **not** have to be proactive as missing rivet has no impact on oil pressure. Replacement can occur during a planned engine rebuild.

Service Parts

- Service parts are offered. See Table 1 for part numbers.
- Rocker lever assembly, top level, and kit part numbers did **not** change. Part numbers within the kits and assemblies did change. See Table 1 for details.

Table 1, Service Parts				
Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
Lever, Rocker	3053476	Yes	Yes	6377069
Lever, Rocker	3053477	Yes	Yes	6377067

Production Status

Implemented for production. See Table 2.

Table 2, Production Information		
ESN First	Build Date ¹	Plant
33233267	August 2023	Daventry Engine Plant
37291483	August 2023	Seymour Engine Plant
¹ Engine build date can be found on engine dataplate.		

Document History

Date	Details
2023-9-5	Module Created