



Technical Service Bulletin

Technical Service Bulletin: TSB240105

Released Date: 18-Aug-2025

New Pre-Lube Pressure Switch

New Pre-Lube Pressure Switch

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- QST30 CM552
- QST30 CM2350 T101
- QST30 CM2350 T103C

Issue Summary

Symptom:

- Engine will **not** start
- Lubricating oil leaking through the pre-lube pressure switch

Root Cause:

- Engine **not** starting- soldering the wires to the internal electrical contacts of the pre lube pressure switch.
- Oil leaks- O-ring and diaphragm hardening because of unsuitable materials.

Verification

- Visually inspect the pre-lube pressure switch to identify the lubricating oil leak through the vent hole on the switch.
- Use multimeter to measure resistance of pre-lube switch when pressure is applied. Variable resistance or infinite resistance indicates poor wire connection.

Resolution

- If customer is experiencing multiple pre-lube pressure switch malfunctions, replace malfunctioning switch with new pre-lube pressure switch.

Service Instructions

- For pre lube pressure switch removal and installation instructions, see corresponding Service Manual. Reference Procedure 007-086 in Section 7.

- Before connecting the pre-lube switch harness to the engine harness, use quick-dry electrical contact cleaner, Part Number 3824510, to remove all dirt and moisture from the pre-lube switch connector and the engine wiring harness connector.

Service Parts

Service parts are offered. See Table 1 for part numbers.

Table 1, Service Parts				
Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
Pre-lube Pressure Switch	4924925	No	No	6396482

Part Inventory Action

Reallocate stock of the existing pre-lube pressure switch, Part Number 4924925, to QSK50 and QSK60 engines.

Production Status

Implemented for production. See Table 2.

Table 2, Production Information			
ESN First	Engine Model	Build Date ¹	Plant
37296673	QST30 CM552	7 April 2025	SEP

¹Engine build date can be found on engine dataplate.

Document History

Date	Details
2024-5-7	Module Created
2025-8-15	Non-Product Problem Solving (PPS)