



Technical Service Bulletin

Technical Service Bulletin: TSB250017

Released Date: 05-Feb-2025

New Accessory Drive Seal: Engine Lubricating Oil Leak

New Accessory Drive Seal: Engine Lubricating Oil Leak

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- KT38
- KTA38
- KTA50
- KTTA38
- KTTA50
- QSK38 CM2150 K106
- QSK38 CM2150 MCRS
- QSK38 CM2350 K125
- QSK38 CM2350 K138M
- QSK38 CM850 MCRS
- QSK50 CM2150 K107
- QSK50 CM2150 MCRS
- QSK50 CM2350 K108
- QSK50 CM2350 K130
- QSK50 CM500
- QSK50 CM850 MCRS

Description of Change

- A new accessory drive seal with a revised design has been released.
- The new accessory drive seal uses a single piece construction.
- To install the new accessory drive seal, a new service tool has been released.

Reason for Change

The existing accessory drive seal can leak engine lubricating oil.

Service Instructions

- All existing pulley part numbers have been obsoleted and superseded by new pulley part numbers.
- New pulleys are sold without a wear sleeve fitted to the pulley shaft, allowing the use of the new accessory drive seal.
- A new pulley **must** be used when installing the new accessory drive seal. A new accessory drive seal installer part number is available and listed in Table 1.
- **Never** remove the wear sleeve from existing pulleys because of the risk of introducing an engine lubricating oil leak path.
- New pulley part numbers are shown in Table 1, allowing cross reference from the existing pulley part numbers.

Service Parts Availability

- Service parts are available. See Table 1 for part numbers.
- Existing part numbers will remain available for service on the KV19 and QSK19 engines **only**.

Table 1, Service Parts

Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
ACCESSORY DRIVE SEAL	3628895	No	No	5694571
ACCESSORY DRIVE SEAL	3628894	No	No	5694571
ACCESSORY DRIVE SEAL INSTALLER	-	No	No	5573466
PULLEY, ACCESSORY DRIVE	3015546	Yes	Yes	3628938
PULLEY, ACCESSORY DRIVE	3018761	Yes	Yes	3015321
PULLEY, ACCESSORY DRIVE	3028587	Yes	Yes	3177006
PULLEY, ACCESSORY DRIVE	3045970	Yes	Yes	3628937
PULLEY, ACCESSORY DRIVE	3179943	Yes	Yes	3628940
PULLEY, ACCESSORY DRIVE	3179944	Yes	Yes	3628939

Table 1, Service Parts					
Part Description	Existing Part Number	Obsolete	Superseded	New Part Number	
PULLEY, ACCESSORY DRIVE	3631843	Yes	Yes	3631844	
PULLEY, ACCESSORY DRIVE	3645612	Yes	Yes	3645579	
PULLEY, ALTERNATOR	3880348	No	No	3875798	
PULLEY, ACCESSORY DRIVE	5538240	Yes	Yes	5538239	
Service Tools and Training Available A new accessory drive seal installer part number is available and listed in Table 1. Production Status Implemented for production. See Table 2.					
Table 2, Production Information					
ESN First		Build Date ¹	Plant		
33227622		21 February 2022	Daventry		
¹ Engine build date can be found on the engine dataplate.					
Publications Affected					
Table 3, Publications Affected					
Manual Type	Engine	Bulletin Number	Procedure Title	Procedure	Section
Service Manual	QSK38/50	4021528	Accessory Drive Seal	Refer to Procedure 001-003 (/qs3/pubsyss2/xml/en/procedures/28/28-001-003.html)	1

Table 3, Publications Affected					
Manual Type	Engine	Bulletin Number	Procedure Title	Procedure	Section
Service Manual	QSK38 CM2150 K106	4332768	Accessory Drive Seal	Refer to Procedure 001-003 (/qs3/pubsy s2/xml/en/pr ocedures/25 1/251-001-003.html)	1
Service Manual	QSK50 CM2150 K107	4332773	Accessory Drive Seal	Refer to Procedure 001-003 (/qs3/pubsy s2/xml/en/pr ocedures/25 3/253-001-003.html)	1
Service Manual	QSK50 CM2350 K108	4332823	Accessory Drive Seal	Refer to Procedure 001-003 (/qs3/pubsy s2/xml/en/pr ocedures/25 5/255-001-003.html)	1
Service Manual	QSK50 CM2350 K130	5504180	Accessory Drive Seal	Refer to Procedure 001-003 (/qs3/pubsy s2/xml/en/pr ocedures/53 6/536-001-003.html)	1
Service Manual	QSK50 CM2350 K130	5504180	Gear Cover, Front	Refer to Procedure 001-031 (/qs3/pubsy s2/xml/en/pr ocedures/53 6/536-001-031.html)	1

Table 3, Publications Affected					
Manual Type	Engine	Bulletin Number	Procedure Title	Procedure	Section
Service Manual	QSK38 CM2350 K138M	5613395	Accessory Drive Seal	Refer to Procedure 001-003 (/qs3/pubsys2/xml/en/procedures/542/542-001-003.html)	1
Service Manual	QSK38 CM2350 K138M	5613395	Gear Cover, Front	Refer to Procedure 001-031 (/qs3/pubsys2/xml/en/procedures/542/542-001-031.html)	1

Document History

Date	Details
2025-1-29	Module Created