



Technical Service Bulletin

Technical Service Bulletin: TSB250131

Released Date: 08-Jul-2025

Steel Edge Bonded Gear Housing Gasket

Steel Edge Bonded Gear Housing Gasket

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- QSK38 CM2150 K106
- QSK38 CM2150 K142M
- QSK38 CM2350 K125
- QSK38 CM2350 K138M
- QSK38 CM2350 K145G
- QSK50 CM2150 K107
- QSK50 CM2150 K140M
- QSK50 CM2350 K108
- QSK50 CM2350 K130
- QSK50 CM2350 K146G

Description of Change

- A steel edge bonded rubber gasket version of the existing gear housing fiber gasket released and added as an optional addition.
- The sealing of the two different gaskets differs significantly therefore the change in gasket material has also driven dimensional changes to the gear housing, gear cover and camshaft cover (gear cover) designs. A shim has also been released to ensure the air gap for the camshaft position sensor is maintained. A procedure currently exists in the service manuals to allow for shimming of the camshaft position sensor without the need for the specific OEM shim.

Reason for Change

Improved lubrication oil sealing between the gear cover and housing and the cylinder block.

Customer Communication

The additional gear housing gaskets are a steel edge bonded rubber gasket and have been released alongside the existing fiber gear housing gasket which will continue to be available as a production and service item for existing engines.

Service Instructions

Table 1 shows where the camshaft position sensor needs to be shimmed. Should an OEM shim **not** be available, a procedure does exist to machine a shim locally to meet specific requirements. See corresponding Service Manual. Reference Procedure 019-363 in Section 19.

Service Parts Availability

Service parts are available. See Table 1 for part numbers.

Table 1, Service Parts

Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
GASKET	3644502	No	No	5539807
COVER, GEAR (Without Camshaft Cover)	3638995	No	No	6389444
COVER, GEAR (With Camshaft Cover)	5694541	No	No	6389476*
HOUSING, GEAR	3176918	No	No	5374581
COVER, CAMSHAFT	5374477	No	No	5539411*
SHIM	-	No	No	6398296

*Shim Required When Using New Part Number

Part Compatibility

- The new steel edge bonded gaskets is **not** to be used with the fiber gasket gear covers and housings. Because of the increased thickness of the steel edge bonded gasket and narrower sealing patterns, contact interactions with the gear train and electronics exist.
- When upgrading engines originally fitted with fiber gear housing gaskets to the new steel edge bonded gear housing gaskets the new gear cover and housing part numbers in Table 1 **must** be used to prevent damage to the gear train and electrical components.

Part Identification

- New part is stainless-steel and is easily recognizable compared to the fiber gasket.
- The part number permanently applied on the steel carrier of the new gaskets.

Production Status

Implemented for production. See Table 2.

Table 2, Production Information

ESN First	Build Date ¹	Plant
33239155	26 May 2025	Daventry

¹Engine build date can be found on the engine dataplate.

Document History

Date	Details
2025-6-26	Module Created

Last Modified: 08-Jul-2025