



Technical Service Bulletin

Technical Service Bulletin: TSB250157

Released Date: 05-Sep-2025

Turbocharger Speed Sensor and Crankshaft Position Sensor Update

Turbocharger Speed Sensor and Crankshaft Position Sensor Update

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- HSK78G CM2358 K129G
- HSK78G CM2358 K171C
- K38 CM2350 K165G
- QSK23 CM2250 K109
- QSK23 CM2350 K127
- QSK23 CM2450 K168G
- QSK38 CM2150 K106
- QSK38 CM2150 MCRS
- QSK38 CM2350 K125
- QSK38 CM2350 K138M
- QSK38 CM2350 XPI
- QSK38 CM850 MCRS
- QSK50 CM2150 MCRS
- QSK50 CM2350 K108
- QSK50 CM2350 K130
- QSK50 CM2350 K146G
- QSK50 CM850 MCRS
- QSK60 CM2150 MCRS
- QSK60 CM2250 K112
- QSK60 CM2350 K117
- QSK60 CM2350 K121
- QSK60 CM2350 K135
- QSK60 CM2350 K136
- QSK60 CM2350 K149M
- QSK60 CM850 MCRS
- QSK60 G CM2358 K110

- QSK78 CM2250 K104
- QSK78 CM2250 K126
- QSK78 CM2250 K137
- QSK78 CM2350 K154C
- QSK78 CM2450 K161G
- QSK78 CM500 MCRS
- QSK95 CM2350 K111
- QSK95 CM2350 K113
- QSK95 CM2350 K128M

Description of Change

- The anodizing layer on the inner side of the aluminum body of the turbocharger speed sensor and crankshaft position has been removed.

Reason for Change

- The anodized aluminum material compromised the epoxy, creating a leak path for water ingress. This caused shorting of the internal electronics, resulting in sensor signal loss, electronic control module (ECM) fault codes, and engine shutdown.

Part Identification

- The change is documented on the sensor using the printed date code. Date codes as follows:
- Crankshaft position sensor part number, 5491808 - Date Code: 25062
- Turbocharger speed sensor part number, 5491809 - Date Code: 25230



Figure 1, Crankshaft Position Sensor Date Code Location.

Production Status

Implemented for production. See Table 2.

Table 2, Production Information		
ESN First	Build Date ¹	Plant
33238971	2 May 2025	Daventry Engine Plant
¹ Engine build date can be found on the engine dataplate.		

Document History

Date	Details
2025-8-21	Module Created