



Technical Service Bulletin

Technical Service Bulletin: TSB250208

Released Date: 26-Feb-2026

New Turbocharger

New Turbocharger

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- QST30 CM552

Description of Change

A new turbocharger has been released to production and the aftermarket for the QST30 CM552 product. The change includes a new turbocharger bearing housing design with new internal lubricating oil drain geometry to address lubricating oil leaks from the turbocharger compressor outlet.

Service Instructions

There is a possibility when installing the new turbocharger that the turbocharger oil drain line flange could interfere with one of the turbocharger turbine housing capscrews. If the turbocharger oil drain line flange can **not** be seated flat against the mounting surface of the turbocharger oil drain outlet, the turbocharger oil drain line flange will need to be modified using the following instructions.

See the QST30 Service Manual, Bulletin 4021539. Refer to Procedure 010-045 in Section 10 to remove and clean the turbocharger oil drain line. Use Clean Care Kit protective caps to keep the engine block oil drain port clean.

With the turbocharger oil drain line removed and cleaned of all residual oil, use tape to cover the inlet and outlet of the turbocharger oil drain line to prevent introduction of debris into oil drain path.

Using a hand file, remove approximately 1.5 mm [0.06 in] from the interfering side of the turbocharger oil drain line flange. See Figure 1.



Figure 1, Visualization of removed material from turbocharger oil drain line flange.

After material has been removed, remove tape from the inlet and outlet of the turbocharger oil drain line.

See the QST30 Service Manual, Bulletin 4021539. Refer to procedure 010-045 in Section 10 to install the turbocharger oil drain line.

Service Parts

Service parts are offered. See Table 1 for part numbers.

Table 1, Service Parts

Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
Aftermarket Turbocharger Kit	5321615	Yes	Yes	6597459
Turbocharger	4042918	Yes	Yes	6596568
Turbocharger	4042919	Yes	Yes	6596569
Aftermarket Turbocharger	4033508	Yes	Yes	6597458

Table 2, Production Information

ESN First	Engine Model	Build Date ¹	Plant
37298583	QST30 CM552	24 November 2025	SEP

Table 2, Production Information			
ESN First	Engine Model	Build Date ¹	Plant
¹ Engine build date can be found on engine dataplate.			

Part Inventory Action
Release strategy is under review.

Document History

Date	Details
2025-11-6	Module Created
2025-11-10	Correcting outfile issue with TSB.
2026-2-2	Non-Product Problem Solving (PPS)