



Technical Service Bulletin: TSB260032

Released Date: 26-Feb-2026

New Lubricating Oil Pan Gasket

New Lubricating Oil Pan Gasket

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- QST30 CM552
- QST30 CM850
- QST30 CM2350 T101
- QST30 CM2350 T103C

Description of Change

A lubricating oil pan gasket is being released as a directional improvement to the sealing of the joint. The new lubricating oil pan gasket has maintained the same 8-piece design but is 0.6mm thinner and a new material.

Service Instructions

Make sure the lubricating oil pan gasket is installed with the "PAN SIDE" stamped text facing the lubricating oil pan.

Service Parts

Service parts are offered. See Table 1 for part numbers.

Table 1, Service Parts

Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
Oil Pan Gasket	3092855	Yes	Yes	6627646

Part Identification

The new lubricating oil pan gasket is approximately 1.0mm in thickness and black in color. It has the text "PAN SIDE" stamped on one side of each individual piece.

The current lubricating oil pan gasket is approximately 1.6mm in thickness and blue in color. It has text including "TS-9016" printed multiple times on one side of each individual piece.



Figure 1, New Lubricating Oil Pan Gasket



Figure 2, Current Lubricating Oil Pan Gasket

Part Inventory Action

Obsolete part numbers in stock are **not** to be used. Obsolete part numbers in stock are to be returned for reimbursement.

Production Status

Implemented for production. See Table 2.

Table 2, Production Information

ESN First	Build Date ¹	Plant
37298055	30 September 2025	Seymour Engine Plant
¹ Engine build date can be found on the engine dataplate.		

Publications Affected

Table 3. Publications Affected

Manual Type	Engine	Bulletin Number	Procedure Title	Procedure	Section
Service Manual	QST30	4021539	Lubricating Oil Pan	Refer to Procedure 007-025	7

Table 3. Publications Affected					
Manual Type	Engine	Bulletin Number	Procedure Title	Procedure	Section
Service Manual	QST30 CM2350 T101	5467179	Lubricating Oil Pan	Refer to Procedure 007-025	7
Service Manual	QST30 CM2350 T103C	6309062	Lubricating Oil Pan	Refer to Procedure 007-025	7

Document History

Date	Details
2026-2-19	Module Created