

|                              |                            |
|------------------------------|----------------------------|
| SAHYADRI PETROCHEMICALS LTD. | Doc No: MAIL-ARC-2024-1187 |
| Email Archive — Engineering  | Rev: - Date: Archived 2025 |
| Classification: INTERNAL     | Page 1 of 1                |

## EMAIL ARCHIVE EXTRACT

Engineering mailbox | Thread re: P-1101A

Exported email thread from the Engineering mailbox archive. Illustrates knowledge that lives only in email and is invisible to the maintenance and safety systems.

**From:** S. Iyer (Reliability) **To:** R. Deshmukh (Rotating Eqp.)  
**Date:** 22-Nov-2024 **Subject:** P-1101A seal failures — we keep treating symptoms  
Ravi — that's the third seal on P-1101A this year. My Nov vibration survey shows 7.1 mm/s, dominant 2x — this is misalignment, not bad seals. Every WO just swaps the cartridge and restarts. Can we get a laser alignment done and confirm the Plan 52 buffer is actually cooling? Otherwise it'll fail again in a few weeks. — Sandeep

**From:** R. Deshmukh **To:** S. Iyer  
**Date:** 25-Nov-2024 **Subject:** RE: P-1101A seal failures  
Agreed. We've never recorded an alignment on this train. I'll plan the laser alignment at the next opportunity window and check the buffer cooler. Let's also raise a proper RCFA — compliance has been asking. — Ravi

[No RCFA or alignment work order was subsequently found in the CMMS as of the Jan-2025 export. The action lived only in this email.]