

Equipment Maintenance Log & Historical Audit - Bay 3 CNC Centers

1. Machine M102 Historical Summary

Machine M102 was installed in Q1 2024. Over the past 6 months, M102 has maintained 94% uptime but experienced two significant downtime events in August 2026 totaling 31.5 hours.

Event 1 (August 12, 2026): 18.2 hours downtime due to cooling-system failure. Root cause was identified as heavy debris accumulation blocking the radiator cooling matrix, causing thermal shutdown E-704.

Event 2 (August 22, 2026): 13.3 hours downtime due to spindle optical sensor calibration drift after a vibration shock.

2. Preventative Action Recommendations

Engineering recommended increasing the cooling system inspection frequency during summer months and installing secondary particulate mesh filters on M102 radiator intakes.