

SMRITI VAN MAYUR VIHAR — INFRASTRUCTURE

Category export · AI Drone Survey · DDA / DTU parameter framework

Site: Smriti Van Mayur Vihar, Mayur Vihar (DDA)

Survey date: 19 May 2026, 16:54-17:35 IST (single-date baseline)

Category: Infrastructure

CATEGORY SCORE				
Indicator	Mean	Min	Max	Rating
Infrastructure	75.9%	49.8%	92.4%	Good

SCENE COVERAGE (park-wide mean)			
Metric	Mean	Min	Max
Paved area	0%	0%	0%

DETECTOR FINDINGS				
Detector class	Records	Mean cond. %	Worst %	Condition
Walking Track	335	52.9	34.4	Poor
Kerb / Edging	991	83.1	73.6	Good
Bench	178	75.4	68.1	Good
Open Gym Equipment	195	81.9	64.9	Good
Pathway Obstruction	1	44.1	44.1	Poor
Paved Area	42	75.3	72.6	Good
Excavation / Disturbed Ground	1	48.1	48.1	Poor
Material Stockpile	0	—	—	Not observed in these clips
Construction Activity	2	32.1	19.8	Critical

ANOMALIES (worst first)					
Priority	Zone	Anomaly	Severity	Cond. %	Suggested action
6	Children's play area	Construction Activity	Critical	19.9	Confirm the works are sanctioned and that a site-safety plan, hoarding and signage are in place. Record against the sanctioned works schedule for contractor verification.
26	Children's play area	Walking Track	High	37.1	Resurface and reinstate the track after the works.
39	Children's play area	Walking Track	High	40.1	Resurface and reinstate the track after the works.
41	Children's play area	Walking Track	High	40.6	Resurface and reinstate the track after the works.
58	Children's play area	Pathway Obstruction	High	44.1	Clear the walking track immediately and provide a signed, barricaded pedestrian diversion.
60	Children's play area	Walking Track	High	44.4	Resurface and reinstate the track after the works.

Priority	Zone	Anomaly	Severity	Cond. %	Suggested action
63	Waterlogged ground	Construction Activity	High	44.6	Confirm the works are sanctioned and that a site-safety plan, hoarding and signage are in place. Record against the sanctioned works schedule for contractor verification.
90	Children's play area	Excavation / Disturbed Ground	Medium	48.2	Barricade and signpost the excavation; reinstate and compact the surface once works are done.
97	Children's play area	Walking Track	Medium	48.5	Resurface and reinstate the track after the works.
109	Waterlogged ground	Walking Track	Medium	49.3	Resurface and reinstate the track after the works.
126	Children's play area	Walking Track	Medium	50.4	Resurface and reinstate the track after the works.
130	Lawns & tree belt	Walking Track	Medium	50.5	Resurface and reinstate the track after the works.
131	Children's play area	Walking Track	Medium	50.6	Resurface and reinstate the track after the works.
148	Children's play area	Walking Track	Medium	52.4	Resurface and reinstate the track after the works.
157	Children's play area	Walking Track	Medium	53.7	Resurface and reinstate the track after the works.
171	Waterlogged ground	Walking Track	Medium	54.5	Resurface and reinstate the track after the works.
174	Children's play area	Walking Track	Medium	54.7	Resurface and reinstate the track after the works.
198	Children's play area	Walking Track	Medium	57.2	Resurface and reinstate the track after the works.
204	Waterlogged ground	Walking Track	Medium	57.7	Resurface and reinstate the track after the works.

RECOMMENDED ACTIONS

#	Priority	Finding	Recommended action	Owner
4	High	A piece of children's play equipment appears collapsed on the ground in the play-area clip, and the sand surface beneath the equipment is bare and hard-packed.	Inspect and make safe immediately - remove or reinstate the fallen unit, and replace the impact-absorbing surface under all play equipment.	Engineering / Works
6	Medium	Pathways and kerb runs show wear consistent with the site record of unmaintained pavement.	Patch and resurface the worst track segments; reset displaced kerb and edging.	Engineering / Works
8	Process	Several items recorded on site have no detector class yet: leaking water pipes, weeds near pathways, gazebo, signpost, street lamp, main gate, monuments, dead trees.	Confirm which of these matter most for the DDA report and they can be added - most are feasible; the pipe in Clip 1 is a clear, high-contrast target.	Survey / Drone Cell

Generated from Smriti_Van_AI_Detection_Report.xlsx · DDA AI Park Monitor. Figures are the park-wide mean across 4 analysed clips, recomputed directly from the detection log rather than the workbook's own summary formulas.