

VASANT UDYAN — INFRASTRUCTURE

Category export · AI Drone Survey · DDA / DTU parameter framework
Site: Vasant Udyan, Vasant Kunj (DDA)
Survey date: 18 May 2026, 15:03-15:07 IST (single-date baseline)
Category: Infrastructure

CATEGORY SCORE					
Indicator		Mean	Min	Max	Rating
Infrastructure		73.5%	36.6%	86%	Fair

SCENE COVERAGE (park-wide mean)					
Metric		Mean	Min	Max	
Paved area		0%	0%	0%	

DETECTOR FINDINGS					
Detector class		Records	Mean cond. %	Worst %	Condition
Walking Track		393	59.3	36.6	Poor
Kerb / Edging		365	80.3	73.4	Good
Bench		160	77.1	70.1	Good
Open Gym Equipment		533	85	75.5	Good
Pathway Obstruction		0	—	—	Not observed in these clips
Paved Area		74	79.4	71.4	Good
Excavation / Disturbed Ground		0	—	—	Not observed in these clips
Material Stockpile		0	—	—	Not observed in these clips
Construction Activity		0	—	—	Not observed in these clips

ANOMALIES (worst first)					
Priority	Zone	Anomaly	Severity	Cond. %	Suggested action
32	Pathways & tree belt	Walking Track	High	43.3	Resurface / patch the track; restore edge definition and camber.
35	Pathways & tree belt	Walking Track	High	44	Resurface / patch the track; restore edge definition and camber.
46	Pathways & tree belt	Walking Track	Medium	45.3	Resurface / patch the track; restore edge definition and camber.
47	Pathways & tree belt	Walking Track	Medium	45.3	Resurface / patch the track; restore edge definition and camber.
55	Pathways & tree belt	Walking Track	Medium	47.1	Resurface / patch the track; restore edge definition and camber.
83	Pathways & tree belt	Walking Track	Medium	51.2	Resurface / patch the track; restore edge definition and camber.
101	Children's play area	Walking Track	Medium	53.5	Resurface / patch the track; restore edge definition and camber.

Priority	Zone	Anomaly	Severity	Cond. %	Suggested action
107	Children's play area	Walking Track	Medium	56.1	Resurface / patch the track; restore edge definition and camber.
109	Pathways & tree belt	Walking Track	Medium	56.6	Resurface / patch the track; restore edge definition and camber.
111	Pathways & tree belt	Walking Track	Medium	57.8	Resurface / patch the track; restore edge definition and camber.
117	Children's play area	Walking Track	Medium	59.4	Resurface / patch the track; restore edge definition and camber.

RECOMMENDED ACTIONS

#	Priority	Finding	Recommended action	Owner
2	High	The site record notes a broken swing, broken tiles on gym equipment and getting worse signboard paint. The detector finds and scores the equipment but cannot itself assert structural damage.	Physically inspect every play and gym unit; use the anomaly register to prioritise the lowest paint-integrity scores. Make any broken unit safe immediately - this is a children's play area.	Engineering / Works
5	Medium	Pathway facilities scores 65.4, notably below the play area, matching the site note of poor pavement condition.	Survey the path network; patch and resurface the worst segments and reset displaced edging.	Engineering / Works
6	Process	No class exists for: broken equipment, signboards, gazebo / pergola, streetlights, dustbins, boundary wall as distinct from kerb, or the waterway condition recorded on site.	Confirm which matter most for the DDA report. 'Broken' is genuinely hard from imagery; a low-altitude pass over the play equipment would serve better than a detector.	Survey / Drone Cell

Generated from Vasant_Udyan_AI_Detection_Report.xlsx · DDA AI Park Monitor. Figures are the park-wide mean across 2 analysed clips, recomputed directly from the detection log rather than the workbook's own summary formulas.