

VASANT VATIKA — ASSET INVENTORY

Category export · AI Drone Survey · DDA / DTU parameter framework

Site: Vasant Vatika, Vasant Kunj (DDA)

Survey date: 18 May 2026, 16:05-16:08 IST (single-date baseline)

Category: Asset Inventory

DETECTOR FINDINGS

Detector class	Records	Mean cond. %	Worst %	Condition
Tree Stem	1900	94.7	53.5	Good
Bench	324	79.1	67.7	Good
Play Equipment	209	82.7	65.9	Good
Open Gym Equipment	288	81.3	66.7	Good
Walking Track	401	56.7	39.9	Poor

ANOMALIES (worst first)

Priority	Zone	Anomaly	Severity	Cond. %	Suggested action
45	Open gym & hedge beds	Walking Track	High	43.6	Resurface / patch the track; restore edge definition and camber.
51	Open gym & hedge beds	Walking Track	Medium	45.4	Resurface / patch the track; restore edge definition and camber.
52	Open gym & hedge beds	Walking Track	Medium	46	Resurface / patch the track; restore edge definition and camber.
78	Fountain & formal garden	Walking Track	Medium	51.1	Resurface / patch the track; restore edge definition and camber.
100	Central lawn & avenue	Walking Track	Medium	52.8	Resurface / patch the track; restore edge definition and camber.
103	Open gym & hedge beds	Walking Track	Medium	52.9	Resurface / patch the track; restore edge definition and camber.
118	Open gym & hedge beds	Walking Track	Medium	54.7	Resurface / patch the track; restore edge definition and camber.
125	Open gym & hedge beds	Walking Track	Medium	55.2	Resurface / patch the track; restore edge definition and camber.
135	Open gym & hedge beds	Walking Track	Medium	55.9	Resurface / patch the track; restore edge definition and camber.
137	Open gym & hedge beds	Walking Track	Medium	56.5	Resurface / patch the track; restore edge definition and camber.
140	Open gym & hedge beds	Walking Track	Medium	56.9	Resurface / patch the track; restore edge definition and camber.
147	Open gym & hedge beds	Walking Track	Medium	58.5	Resurface / patch the track; restore edge definition and camber.

RECOMMENDED ACTIONS

#	Priority	Finding	Recommended action	Owner
1	High	The open gym zone has 43% bare ground and 6.3% lawn with an watering score of 39.1, while the rest of the park sits above 90. The failure is localised to the area around the equipment pad.	Extend the watering that works elsewhere in the park into the gym zone, then decompact and re-turf. Consider a defined hard or soft-surface apron around the equipment where foot traffic concentrates.	Horticulture / Engineering

#	Priority	Finding	Recommended action	Owner
3	Medium	The site record notes getting worse paint on the gym equipment. The equipment was detected and scored on paint integrity.	Inspect the lowest paint-integrity scorers in the anomaly register; sand, prime and repaint, and check fixings and footings.	Engineering / Works

Generated from Vasant_Vatika_AI_Detection_Report.xlsx · DDA AI Park Monitor. Figures are the park-wide mean across 3 analysed clips, recomputed directly from the detection log rather than the workbook's own summary formulas.