INVOICE



Bill To

Melissa Ortega

Steve Tousain, MasterPlumbers Lic. M16380 747 Pecan Ln, Cottonwood Shores, Tx 78657

Phone: (830) 385-1706

Email: absoluteplumbingtx@gmail.com

Web: Texas Board of Plumbing www.TSBPE.org

Payment terms Due upon receipt Invoice # 883
Date 07/24/2025

Description	Total
Recommended Plumbing Repairs 805 High Mesa	\$0.00
(All prices quoted for repairs are not final until assessed in person)	
Vacuum Breaker Install 2 anti-siphon vacuum breakers at hosebibs	\$30.00
Master Toilet Toilet was slightly loose at base. Tightened flange bolts	\$0.00
Water Leak 2 small leaks where 3/4 PVC water supply enters house under water heater area.	\$150.00
Replaced approximately 8 feet of line & adapters	
Bathroom Sink Drain Repair	\$85.00
Replaced unsecured flexible accordion style drain under guest bath sink with appropriate offset tubular fittings	

Temperature & Pressure Relief Drain Water heater T&P drain is piped into crawlspace under house. Installed CPVC to extend drain out from under house & terminated visibly outside 6" above ground	\$160.00
Dishwasher	\$125.00
Replaced dishwasher with customer supplied unit	
Looped drain up under sink for anti siphon	
Toilet Replacement	\$155.00
Install customer supplied toilet in guest bath. Includes new wax seal, toilet bolts and supply line & caulking	
Secure Hosebib	\$50.00
Front hosebib spigot needs to be shortened & secured from crawlspace	
Also added blocking & clamped rear hosebib that was loose	

\$0.00

Other items on inspection report addressed as follows -

Notes:

- At water meter, no user shut off valve; Since utility shut off valve is readily accessible & operable, it is sufficient as is - unless directed otherwise by local municipality.
- Incomplete insulation on water lines in crawl space; While it is recommended, all pipes seem to be in good condition & somewhat protected in a skirted crawl space area.
- Water observed in sewer clean out; No immediate issue seems to be present since drains appeared to flow freely through horizontal area to septic. There is most likely a slight belly or flat spot in driveway area but is easily accessible with multiple clean outs
- Water Heater has no expansion tank or pan; While these are standard for new installations, they do not necessarily pose a threat to safety as the temperature pressure relief drain does
- Hot & cold to guest tub are reversed; Since each handle is adequately labeled, this would be a personal preference

Total	\$755.00
Subtotal	\$755.00

Payment Summary

Remaining Amount	\$0.00	
Paid Total	\$755.00	
07/24/2025 - Credit Card or PayPal	\$755.00	

When paying with Credit Card, Please add 3% processing fee

ocument.		

By signing this document, the customer agrees to the services and conditions outlined in this