

Corrective Maintenance Report - Fiber Splice Repair TG-LEK-A / Junction LJ-7

Document Code: CMR-LEK003-20260430

Reference Incident: INC-2841
Site: Junction LJ-7, Lekki Phase 1 Corridor
Date of Repair: April 30, 2026
Engineer: Chukwuemeka Eze (Field Engineer, Team Lead)
Reviewed by: Ibrahim Musa (Transmission Engineer)

1. Fault Description

Backhaul fiber cable TG-LEK-A was severed at junction LJ-7.
Cause: Third-party civil excavation by Dangote road contractor. Permit LASG-CW-2026-1847 was active in the area at the time of damage.

2. Fault Classification

External - Third Party Damage

3. Affected Equipment

- Fiber cable TG-LEK-A
- Splice joint SJ-7-003
- Conduit section C-7-012

4. Work Scope

- Emergency fiber splice repair
- Conduit section repair
- Re-routing around damaged section

5. Materials Used

Material	Quantity
Splice protection sleeve	2

MTN Nigeria

Conduit coupling	1
Fiber end-face cleaner	-
Index gel	-

6. Repair Procedure

1. Conducted OTDR trace to confirm cut point
2. Exposed damaged cable section
3. Cleaned fiber ends
4. Performed fusion splice
5. Applied splice protection sleeve
6. Re-sealed conduit with coupling and gel
7. Conducted OTDR re-test
8. Restored service after soak period

7. Pre/Post Test Results

Test Parameter	Before Repair	After Repair
OTDR Loss	14.8 dB	4.2 dB
Packet Loss	60%	0.8%

8. Duration

Fault reported: 16:48
Repair completed: 17:33
Service restored: 17:38 (after soak period)

9. Preventive Recommendation

- Install warning marker posts at junction LJ-7
- Notify Lagos State authorities on all future civil permits in this corridor

10. Sign-off

Engineer:
Chukwuemeka Eze

MTN Nigeria

Field Engineer (Team Lead), MTN Nigeria

Reviewed by:

Ibrahim Musa

Transmission Engineer, MTN Nigeria