

Environmental Incident Report - Diesel Fuel Spill at TWR-LAG-W-014

Document Code: EIR-LAGW014-20260318

Prepared by: Chukwuemeka Eze

Reviewed by: Dr Emeka Nwachukwu

Incident Date: March 18, 2026

1. Incident Description

During routine fuel delivery at TWR-LAG-W-014 (Surulere), the fuel supplier overfilled the main tank. The overflow valve was partially blocked, resulting in approximately 35 litres of diesel spilling onto the concrete apron.

2. Discovery

The spill was discovered by Babatunde Okafor upon site arrival at 09:45. The supplier driver had already departed.

3. Immediate Response

- Spill contained using absorbent pads from the site emergency kit.
- Bunded area successfully contained spill within site boundary.
- No fuel reached soil or drainage.

4. Spill Assessment

- Volume: 35 litres diesel.
- Location: Concrete apron within bunded area.
- Impact: No soil or groundwater contact.

5. Clean-up Actions

- Absorbent pads deployed (8 pads used).
- Concrete surface cleaned with industrial degreaser.
- Contaminated pads placed in sealed hazardous waste drums (2 x 25L drums).

6. Waste Disposal

Contaminated materials collected by Cleanville Environmental Services on March 20, 2026 under permit no: LASEPA-2025-0441.

7. Root Cause

Supplier driver used incorrect fill adapter - missing anti-overfill mechanism on this fuel coupling.

8. Regulatory Notification

LASEPA (Lagos State Environmental Protection Agency) notified by email on March 18, 2026 at 14:30. Acknowledgement received. No further action required given contained spill.

9. Corrective Actions

- Retrofit anti-overfill coupling on all Lagos West site fuel fill points.
- Brief all fuel suppliers on MTN fill procedure.
- Inspect bunding condition at all Lagos West sites.

10. Photographs

The following items were photographed as evidence:

1. Spill area on concrete apron.
2. Blocked overflow valve.
3. Absorbent pads deployed during containment.
4. Sealed hazardous waste drums.
5. Cleaned concrete apron post-degreasing.

11. Sign-off

Prepared by:

Chukwuemeka Eze

Field Engineer Team Lead

Reviewed by:

Dr Emeka Nwachukwu

Compliance Manager

Date: March 18, 2026