

Site Visit Report - TWR-LAG-W-031 Preventive Thermal Inspection

Document Code: SVR-LAGW031-20260501

Site: TWR-LAG-W-031 (Yaba North)

Date: May 1, 2026

Time: 15:30 - 17:00 WAT

Engineer: Fatima Aliyu, Field Technician

Supervised by: Chukwuemeka Eze, Field Team Lead

1. Purpose

Preventive thermal inspection triggered by elevated temperature readings observed on NOC dashboard.

2. Site Condition

- Outdoor Temperature: 34C (hot day).
- Equipment Room Ventilation: Running, but one of two cooling fans was seized and not rotating.
- General Condition: Equipment room dusty, filters overdue for cleaning.

3. Fault Found

Fan unit FA-2 motor seized due to bearing failure. Cooling capacity reduced by approximately 50%.

4. Temperature Readings (Before Repair)

Component	Temperature
Ambient	34C
Equipment Room	41C
PA Module	71C
BTS Cabinet	68C
Rectifier	52C

5. Corrective Action

Replaced FA-2 fan unit with spare carried in vehicle (Part No: FAN-MTN-240V-3PH). Tested new fan and

Site Visit Report - TWR-LAG-W-031 Preventive Thermal Inspection

confirmed operational. Temperatures began to drop within 30 minutes.

6. Verification Readings (30 min After Repair)

Component	Temperature
Equipment Room	33C
PA Module	61C
BTS Cabinet	57C

7. Additional Checks

- Cleaned air filters (very dusty, last cleaned 5 months ago).
- Inspected all cable terminations - all secure.
- Checked earthing - satisfactory.

8. Parts Used

- 1 x Fan Unit FAN-MTN-240V-3PH
- Air filter cleaning kit

9. Parts to Order

Recommended ordering spare FA-1 fan unit for this site to ensure redundancy.

10. Time Log

Event	Timestamp (WAT)
Arrival on site	15:30
Fault identified	15:40
Fan replacement started	15:50
Fan replacement ended	16:25
Verification readings	16:55
Departure	17:00

Site Visit Report - TWR-LAG-W-031 Preventive Thermal Inspection

11. Sign-off

Engineer: Fatima Aliyu

Role: Field Technician

Signature: Fatima Aliyu

Date: 2026-05-01

Supervised by: Chukwuemeka Eze

Role: Field Team Lead

Signature: Chukwuemeka Eze

Date: 2026-05-01