

SERVICE CENTRE REPORT

Customer	Entelso Pty Ltd
Model No.	8900-E
Serial No.	81501040
Date Received	08-December-2020
Date Completed	18-February-2021
Job Reference	86815

Condition As Received Into Vicom Store	No apparent damage
Accessories Included With Equipment	Carton
Customer Special Instructions	Return on Vicom freight, Attn: Andrea Aguilar

A. - REPORTED FAULTS AND WORK REQUIRED:

1. We are experiencing intermittent issues with this scanner (signal dropping out, inconsistent readings). It seems to be an issue with high bands for LTE. We are missing readings in some areas or the readings (RSRP) decrease, however, UMTS850 and UMTS2100 are good. The antenna has been changed however the results are the same.

B. - UNREPORTED FAULTS (Faults found at Vicom):

2. None.

C. - ASSESSMENT NOTES:

1. Despite extensive testing we have not been able to replicate the fault with the unit.
The unit was tested over many days and the sweep data collected analysed and no issues occurred.
We also have applied a CW signal at 1725MHz to RF1 and RF2

Applied Signal	RF1	RF2
-32.18	-32.28	-32.26
-42.22	-42.27	-42.37
-52.2	-52.49	-52.34
-62.16	-62.41	-62.31
-72.2	-72.44	-72.31
-82.3	-82.5	-82.53
-92.2	-92.12	-92.16
-102.43	-102.68	-103.03
-112.41	-110.15	-110.86

If a problem occurs in the future please contact ASAP.
We will require the saved scan data (i.e. not exported data) so we can replay the scan and see what happened and analyse it.

D. - DETAILS OF WORK DONE:

1. The unit has been tested and no fault became apparent.

As per discussions with service support, should further problems arise please feel free to contact serviceaus@vicom.com.au

If you experience a problem with this unit:

Please go to <http://www.vicom.com.au/problem-report> and fill in the form. Do not return the unit to Vicom until you have been contacted by Vicom to do so. Sometimes it is possible to resolve issues by phone, and if so this expedites resolution. Please give the name and phone number of the person who can operate the unit while it is being discussed with Vicom technical staff by phone.