

U3 Platform 1.0 SDK

DAPI DLL Release Notes

Version 1.0.3 May 2006



DOCUMENT CONTROL INFORMATION

Document No.: RLN-SDK10R100506-009

	Title	Name	Date
Issued by:	U3 Chief Architect	Daniel Goodman	September 2005
Edited by:		Arik Priel	January 2006
Edited by:		John Bruzas	May 2006



Table of Contents

1	Int	roduction	1
		st of Document Versions	
		Documents	
		Device API (DAPI)	
		evice API DLL Release Notes	



1 Introduction

This document includes the release notes for the May 2006 release of the U3 Platform Software Developer Kit Version 1.0 (U3 Platform 1.0 SDK).

Section 2 - Lists all included documentation, document versions, all DAPI files and versions.

Section 3 - Lists DAPI DLL release notes

2 List of Document Versions

The September 2005 release of the U3 Platform 1.0 SDK includes the following document and file version

2.1 Documents

Title	Number	Ver	Rev	File name	
Developer Guide	04-UM-0605-10	1.0	1.0	DeveloperGuide_1.0r1.pdf	
DAPI Reference Guide	04-UM-0605-00	1.0.1	1.0	DAPIReferenceGuide_1.0.1r1.pdf	
Application Deployment Guide	04-UM-0405-00	1.0	4.0	ApplicationDeploymentGuide_1.0r4.pd	
Release Notes	RLN- SDK10R10050 6-009	1.0.3	n/a	ReleaseNotes_1.0.3.pdf	

2.2 Device API (DAPI)

DAPI Release File version		Size	Signed	Filename	
1.0.3	1.0.3.0	1.08 MB (1,136,208 bytes)	Yes ("U3 LLC")	u3dapi10.dll	
			Wednesday, May 10, 2006 9:12:35 AM		
1.0.2	1.0.2.0	985 KB (1,009,232 bytes)	Yes ("U3 LLC")	u3dapi10.dll	
			Tuesday, February 16 2006 14:22:51		
1.0.1	1.0.1.0	985 KB (1,009,232 bytes)	Yes ("U3 LLC") Monday, September	u3dapi10.dll	
			19, 2005 1:45:26 PM		



3 Device API DLL Release Notes

1.0.3

Unique ID is now consistent between Guest and Admin mode on all devices.

1.0.2

 Fixed: While running DAPI under non-admin account, explicit call to Win32 FreeLibrary method can result with a deadlock.

1.0.1

- Calling dapiSetPrivateAreaPassword after device reached MAX_NOA value, the new private area will remain un-formatted and the function will return a S_OK [0x00000000] result instead of a DAPI_E_FORMAT_FAIL [0x80040213] error result.
- After successfully calling dapiLogoutPrivateArea from a removable domain containing a
 full private area on Windows XP Service Pack 2, the file system is not refreshed and the
 file names are shown after logout. No action can be performed on the files and volume is
 fully secured.
- DAPI will not work on Windows 2003 Server in user mode if hyper-threading is enabled.
 If hyper-threading is disabled, DAPI will work properly in user mode. Hyper-threading is fully supported in admin mode.
- DAPI functions should not be called from within the DAPI callback function. The device handle should be passed to another thread or sent in a windows message, and used to call the DAPI function outside the callback.
- Calling dapiReadTextCookie or dapiReadBinaryCookie with a NULL buffer value and a
 count variable containing a zero value will return a DAPI_E_BUFFER_TOO_SMALL
 result instead of the expected S_OK. The value of the nCount parameter is correctly
 returned and should be used to determine the correct buffer size of pass to the function
 to perform the actual read as documented.
 - The sample in Section 6.3 of the DAPI Reference Guide will fail because of this error.



U3 303 Twin Dolphin Drive, Suite 200 Redwood City, CA 94065 1-800-837-3654, info@u3.com

For more information, visit $\underline{www.u3.com}$