



Home Inspection Summary Report

7 Aster Way, Riverside Heights, CA 95041 · Prepared for Daniel & Priya Okafor (Buyers)

INSPECTION DATE	WEATHER	YEAR BUILT	APPROX. SQ FT
June 13, 2026 · 9:00 AM	Clear, 64°F, dry	2003	2,040
FOUNDATION	UTILITIES ON	OCCUPANCY	REPORT #
Slab-on-grade	Yes — all	Furnished, occupied	CR-26-0613-AW

● Satisfactory — functioning as intended ● Monitor — service or watch ● Repair — action recommended

ROOF & ATTIC

Component	Flag	Observation
Roof covering	Satisfactory	Architectural asphalt shingles, ~10 yrs of remaining service life. No active leaks observed; flashing intact at penetrations.
Gutters & downspouts	Monitor	Functional; minor granule debris in NE gutter run. Recommend seasonal cleaning to maintain drainage.
Attic ventilation & insulation	Satisfactory	R-38 blown-in insulation, even coverage. Ridge and soffit venting adequate; no moisture staining on sheathing.

EXTERIOR, GROUNDS & DRAINAGE

Component	Flag	Observation
Siding & trim	Satisfactory	Fiber-cement siding in good condition; caulking sound at trim joints.
Grading / drainage	Repair	Negative grade at the NW corner directs runoff toward the foundation. Recommend re-grading to establish 6" fall over the first 10 ft away from the structure.
Walkways & patio	Satisfactory	Paver patio level; no significant trip hazards.

STRUCTURE

Component	Flag	Observation
Foundation	Satisfactory	Slab; no significant cracking or differential movement observed at accessible areas.
Framing (visible)	Satisfactory	Visible framing in attic and garage shows no sagging, rot, or fastener failure.

ELECTRICAL

Component	Flag	Observation
Service & panel	Satisfactory	200A main panel (Square D), copper branch wiring, properly labeled, no double-taps.
GFCI / AFCI protection	Repair	Minor GFCI deficiencies: kitchen island receptacle and exterior patio receptacle did not trip on test. Recommend a licensed electrician replace/verify GFCI protection at these locations.
Smoke / CO detectors	Monitor	Present on each level; two units past 10-yr date. Recommend replacement.

PLUMBING

Component	Flag	Observation
Supply & drains	Satisfactory	PEX supply, ABS drains; functional flow and drainage at all fixtures, no active leaks under sinks.

Water heater	Repair	40-gal gas unit, manufacture date 2014 (≈12 yrs) , at/near end of typical service life. T&P valve and seismic strapping present. Budget for replacement.
--------------	--------	---

HVAC

Component	Flag	Observation
Heating (forced air)	Satisfactory	Gas furnace (2019), responded to thermostat, adequate temperature rise across plenum.
Cooling (central A/C)	Satisfactory	Condenser (2019) cooled appropriately; ~18°F split measured. Filter clean.

INTERIOR

Component	Flag	Observation
Walls, ceilings, floors	Satisfactory	No active moisture staining; floors level. Cosmetic wear consistent with age.
Windows & doors	Monitor	One guest-bath window slider sticks; lubrication recommended. Failed seal (fogging) on one dining window pane.

Photo 1 — NW corner grading

Photo 2 — Water heater data plate

Photo 3 — Kitchen island GFCI

Photo 4 — Fogged dining pane

SUMMARY OF RECOMMENDED REPAIRS		
Item	Priority	Recommended action
Negative grading at NW corner	HIGH	Re-grade for positive drainage away from foundation.
GFCI protection (kitchen island, patio)	HIGH	Licensed electrician to replace/verify GFCI devices.
Water heater (≈12 yrs)	MEDIUM	Budget for replacement within 12 months.
Smoke/CO detectors past date	MEDIUM	Replace two expired units.
Fogged dining window pane	LOW	Replace insulated glass unit at convenience.
Gutter debris / sticking window	LOW	Routine maintenance.

This summary accompanies the full narrative report and is not a warranty, guarantee, or code-compliance certification. Inspection is limited to readily accessible, visually observable components on the date of inspection per CREIA Standards of Practice. Cedar Ridge Home Inspections · (415) 555-0414 · ray@cedarridgeinspect.com · Report #CR-26-0613-AW.